




CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	EGYPTIAN MAINTENANCE COMPANY			Job Number:	QC-EMC-03-24-0093		
Date of Examination:	17.03.2024	Location:	EMC YARD	Certificate No:	QC-EMC-03-24-0093/13		
Serial Number:	QTY	Description		SWL	Date of last thorough examination		
2103208 2103202 2103223 2103217	04	VERTICAL PLATE LIFTING CLAMP Manufacturer: GRIPTION Jaw Opening: 0-30 mm Safety Factor: 4:1 Location: Store		2 TON	13.09.2023		
Reference Standard:		BS EN 13155: 2003+A2:2009 / EN 12195					
Is this the first examination after Installation or assembly at a new site or location?		YES		NO	√	Was the examination carried out: Within an interval of 6 months?	
						YES	√
If the answer to the above question is YES has the equipment been installed correctly?		YES		NO		With an interval of 12 months?	
						YES	√
						In accordance with an examination scheme?	
						YES	√
						After the occurrence of exceptional circumstances?	
						YES	√
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE							
Is the above a defect which is of immediate danger to persons:						YES	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:							
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory							
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	√
						NO	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mahmoud Ali	Mohamed Abdulla		11.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

