

**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657


Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

| | | | | | |
|----------------------|---------------|-----------------|---------------|-----------------|-------------------------|
| Date of Examination: | 25-APRIL-2024 | Date of Report: | 25-APRIL-2024 | Certificate No: | QC-24/HALL-TSS-2024-001 |
| Client Name: | HALLIBURTON | Location: | TSS WORKSHOP | Job Number: | 25042024 |

| Serial Number: | QTY | Description | Manufacture date: |
|--|-----|--|-------------------|
| 3929 3942 3962 3946 3949 3932 3963 3950 3964 3952 3960 | 11 | <p>ENDLESS POLYSTER ROUND SLING FLOW LINE SAFETY RESTRAINTS</p> <p>MANUFACTURE: DELTAPLUS REF(WALTRS050600M SIZE:TRS 5T x 6M EWL(Circ. 12m) type: tubular round sling Colour: RED SWL: 5000 KG</p> <p>SAFTEY FACTOR (7:1)</p>  | APRIL-2023 |

| | |
|---------------------|--------------|
| Reference Standard: | BS EN 1492-2 |
|---------------------|--------------|

| | | | | | | | | |
|---|-----|----|---|---|--------------------------------|-----|----|----|
| Is this the first examination after Installation or assembly at a new site or location? | YES | NO | ✓ | Was the examination carried out: Within an interval of 6 months? | YES | ✓ | NO | ✓ |
| | | | | | With an interval of 12 months? | YES | | NO |
| If the answer to the above question is YES has the equipment been installed correctly? | YES | NO | | In accordance with an examination scheme? After the occurrence of exceptional circumstances? | YES | ✓ | NO | |
| | | | | | YES | | NO | ✓ |

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES NO ✓



Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) N/A

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE? YES NO

| | | | |
|-----------------------------------|--|--|---|
| Name of Inspector: | Name of person authenticating this report: | Signature & Stamp: |  |
| ASHRAF ELSAID | AIZAZ FARHAT |  | |
| Date of Next Through Examination: | 24-OCT-2024 | | |

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location at the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



**AI TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED**

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

