




## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Hong Hua Oil& Gas Engineering Services Ltd	<b>Job Number:</b>	QC-HH-03-24-0113/01
<b>Date of Examination:</b>	29.03.2024	<b>Location:</b>	DQ HH029
<b>Certificate No:</b>	QC-HH-03-24-0113		
<b>Serial Number:</b>	<b>QTY</b>	<b>Description</b>	<b>Capacity</b>
22155	01	Fall Arrestor  Manufacture: SALA Date of Manufacture: 05.2020 Length: 175 FT Dia Of Wire: 6 MM Model: 3400650 Lot No: 20051979	191 KG
<b>Date of last Thorough examination</b>	N/A		
<b>Reference Standard:</b>	BS EN 360:2002		
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓
	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓
	YES	NO	✓
Was the examination carried out: Within an interval of 6 months?			
Was the examination carried out: With an interval of 12 months?			
In accordance with an examination scheme?			
After the occurrence of exceptional circumstances?			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>			
Is the above a defect which is of immediate danger to persons:			YES NO ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory			
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>			YES ✓ NO

REV: 01 Dated: 20 June 2022

<b>ASNT Level II Inspector Name:</b>	<b>Authenticating This Report:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
Khalid Mahmoud	Mohamed Abdulla		28.09.2024

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

