


LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Al-Karrar Engineering Co.			Certificate No:	QC-J-4-2024-0030/01
Date of Examination:	22.04.2024	Location:	QC Yard	Job Number:	QC-J-4-2024-0030
Equipment Serial No:	677203			SWL:	1000 KG
Description of Equipment	Diesel Powered Hydraulically Operated Telescopic Boom Mobile Elevating Work Platform Manufacturer Date: AICHI/ 2002 Model: TZ16A Platform Working Height: 16.6m Max. Work Range (1000 Kg): 7.5m Max. Outreach (100 kg): 10.4m Boom Length: 4.33 to 12.31m Extension & Recreation Speed: Extend 40 sec / Retract 40 Sec Date of Manufacture: 2002 Registration No: A 42689 BASRA				
Ref. Standard	BS EN 280:2013 + A1:2015				
Date of Last Examination:	29.10.2023		Date of Last Proof Load Test:	03.05.2023	
Examination Type	Pass	Fail	Notes		
Operational (No Load)	✓		Elevating Work Platform Found Satisfactory For Further Use.		
Performance Test (Rated Capacity)	✓		Elevating Work Platform found to be acceptable to lift 100 % from SWL .		
Proof Load Test (1.1 x Rated Capacity)	--		Proof Load Test Shall Be Done After any Repair/ Modification		
Is this the first examination after Installation or assembly at a new site or location?		YES ☐ NO ☒		Was the examination carried out:	
				Within an interval of 6 months?	
				YES ☒ NO ☐	
If the answer to the above question is YES has the equipment been installed correctly?		YES ☐ NO ☐		With an interval of 12 months?	
				YES ☐ NO ☒	
				In accordance with an examination scheme?	
				YES ☒ NO ☐	
				After the occurrence of exceptional circumstances?	
				YES ☐ NO ☒	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES ☐	NO ☒
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
In the light of inspection findings subject Mobile Elevating Working Platform (MEWP) was Inspected visually, operationally and performance test was performed where no defects were observed during testing Hence, it was found satisfactory and fit for intended use					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES ☒	NO ☐

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Aizaz Farahat	Mohamed Abdulla		21.10.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Al-Karrar Engineering Co.	Location:	QC Yard
Description of Equipment:	Mobile Elevating Working Platform (Man Lift)	Serial No:	677203
Date of Examination:	22.04.2024	Certificate No:	QC-J-4-2024-0030/01
		SWL:	1000 KG

MEWP INSPECTION CHECKLIST

No	COMPONANT CHECKS	RESULT	COMMENTS
DATA PLATE			
1	WHEELS & TYRES	√	
2	ANGLE INDICATOR	√	
3	BOOM LENGTH INDICATOR	√	
4	OPERATING LEVERS & PEDALES	√	
5	LIGHT INDICATOR & HORN	√	
6	WINDOW WIPERS & MIRROR	√	
7	INTEGRITY OF CHASSIS	√	
8	OUTRIGGERS & HOSUSING	√	
9	LEVEL INDICATORS	√	
10	LIGHTS & HORN	√	
11	HYDRULIC SYSTEM	√	
12	OPERATOR MANUAL & LOAD CHART	√	
13	SAFE LOAD INDICATOR	√	
14	PLATFORM DECK & ACCESS	√	
15	BOOM LIFT	√	
16	WEAR PADS	√	
17	HYDRAULIC HOSES	√	
18	BOOM SECTION FOR DAMAGE	√	
19	SLEW MOTOR & GEAR	√	
20	OIL LEAKAGES OF OPERATION	√	
21	BASKET CONDITION	√	
22	GENERAL CONDITIONS	√	
23	EMERGENCY LOWERING SYSTEM	√	

NOTE:

* MEWP visual, function & performance test were carried out and found accept at the time of inspection.

Key Category:

1 = Immediate action	2= Action within ...	3= Worn/Serviceable	✓ No Apparent Defects	N/A = Not Applicable
----------------------	----------------------	---------------------	-----------------------	----------------------

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Aizaz Farahat	Mohamed Abdulla		21.10.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Al-Karrar Engineering Co.	Location:	QC Yard
Description of Equipment:	Mobile Elevating Working Platform (Man Lift)	Serial No:	677203
Date of Examination:	22.04.2024	Certificate No:	QC-J-4-2024-0030/01
		SWL:	1000 KG

PICTORIAL



ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Aizaz Faraht	Mohamed Abdulla		21.10.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.