




## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	IBC Izdehar Elbasra Company			<b>Job Number:</b>	QC-IBC-04-24-0067		
<b>Date of Examination:</b>	15.04.2024	<b>Location:</b>	QC Yard	<b>Certificate No:</b>	QC-IBC-04-24-0067-01		
<b>Serial Number:</b>	<b>QTY</b>	<b>Description</b>			<b>SWL</b>	<b>Date of last thorough examination</b>	
SC01 SC02	02	TWO LEG CHAIN SLINGS C/W SELF LOCKING HOOK  C/W Chain Connector and Master Link At Top & C/W Two Hooks AT Bottom  Manufacture: Safety Marine Diameter: 16 MM Length: 8.5 M Grade: 80			11.2 TON	14.04.2023	
<b>Reference Standard:</b>		BS EN 818-1/4, ASME B30.9					
Is this the first examination after Installation or assembly at a new site or location?		YES		NO		✓	
If the answer to the above question is YES has the equipment been installed correctly?		YES		NO		✓	
				Was the examination carried out:			
				Within an interval of 6 months?		YES ✓ NO	
				With an interval of 12 months?		YES NO ✓	
				In accordance with an examination scheme?		YES ✓ NO	
				After the occurrence of exceptional circumstances?		YES NO ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>							
Is the above a defect which is of immediate danger to persons:						YES	NO ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:							
Particulars of any tests carried out as part of the examination: (If none state NONE)							
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory							
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>						YES	NO ✓

REV: 01 Dated: 20 June 2022

<b>ASNT Level II Inspector Name:</b>	<b>Authenticating This Report:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
Khalid Mahmoud	Mohamed Abdulla		14.10.2024

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

