



CERTIFICATE OF THOROUGH EXAMINATION


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Al- karrar Engineering Company		Certificate No:	QC-J-3-2024-0019/01
Date of Examination:	27.03.2024	Location:	Al- karrar Yard	Job Number: QC-J-3-2024-0019

Serial Number:	QTY	Description	MBL	Date of last Thorough examination
A01 A02	02	Two Leg Chain Sling Chain DIA: 10 MM Length: 3.30 M Grade: 80 Safety Factor: 4:1 MASTER LINK C/W CHAIN CONNECTOR AT THE TOP AND CLEVIS SELF-LOCK HOOK AT THE BOTTOM	3.15 TON	25.04.2022

Reference Standard:	BS EN 818-4:1996+A1:2008
----------------------------	--------------------------

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	✓	NO				
					Within an interval of 12 months?	YES		NO	✓		
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	✓	NO				
					YES		NO	✓			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE											
Is the above a defect which is of immediate danger to persons:								YES		NO	✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						N/A					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:											
Particulars of any tests carried out as part of the examination: (If none state NONE)											
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory											
IS THIS EQUIPMENT SAFE TO OPERATE?								YES	✓	NO	

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		26.09.2024

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

