




## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	AL Karrar Company El Basra-Iraq			<b>Job Number:</b>	QC-J-4-2024-0026
<b>Date of Examination:</b>	12.04.2024	<b>Location:</b>	QC Yard	<b>Certificate No:</b>	QC-J-4-2024-0026-07
<b>Serial Number:</b>	<b>QTY</b>	<b>Description</b>		<b>SWL</b>	<b>Date of last thorough examination</b>
CSK01 CSK02	02	Two Leg Chain Sling  Master Link C/W Chain Connector at The Top and Clevis Self Lock Hook at Bottom Manufacture: Safety Marine Service Grade: 80 Safety Factor: 4:1 Dia: 10 MM Length: 4.45 M		4.25 Ton	12-10-2023
<b>Reference Standard:</b>		<b>BS EN 818-4:1996+ A1:2008</b>			
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	Was the examination carried out: Within an interval of 6 months?	YES
				With an interval of 12 months?	YES
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO	In accordance with an examination scheme?	YES
				After the occurrence of exceptional circumstances?	YES
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>					
Is the above a defect which is of immediate danger to persons:				YES	NO
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>				YES	NO

REV: 01 Dated: 20 June 2022

<b>ASNT Level II Inspector Name:</b>	<b>Authenticating This Report:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Thorough Examination:</b>
Mahmoud Ali	Mohamed Abdulla		11.10.2024

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

