Al TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com





CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	22-04-2024		Date of Report:	22-04-2024	Certificate No:	QC-HALL-2024-01		0165-19		
Client Name:	HALLIBURTON		Location:	HPS YARD	Job Number:	QC-H	1-0165			
Serial Number:	QTY	Description					Date of last thorough examination			
188892-26 1884609-18 1888392-24 1884296-25 1884296-23 1888392-28	06	ENDLESS POLYSTER ROUND SLING FLOW LINE SAFETY RESTRAINTS MANUFACTURE: WEIR SPM EFFECTIVE LENGTH: 20 FT PN: P23625-D					28-10-2023			
Reference Standard	:	PROCEDURE	HSE-0420C REV 1							
Is this the first examination after Installation or assembly at a new site or location? If the answer to the above question is YES has the equipment been installed correctly?			YES NO	✓ Within an interval of 1 With an interval of 1 In accordance with a After the occurrence circumstances?				NO		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the NONE) NONE Is the above a defect which is of immediate danger to persons: Y) \		
Is the above a defect which		et but could be	ecome a danger to pers	sons	YES by:	_				
(If YES state the date by who Particulars of any repair, rer		r alteration red	quired to remedy the d	efect identified above:	·					
Particulars of any tests carri The subject Items were insp satisfactory	ied out oected \	as part of the ϵ /isually and din	examination: (If none st	tate NONE)	· · · · · · · · · · · · · · · · · · ·					
IS THIS EQUIPMENT SAFE TO OPERATE?			75			YES V	NC)		
Name of Inspector:			wame of person aut	henticating this report:	Estamul Company		被动	表記里		
AIZAZ FRAHT			ASHRAF ELSAID Signature & Stamp:							
Latest date by which next thorough examination must be carried out: 21-10-2024										

REV: 00 Dated: 30 May 2021

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





















Al TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com





CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	22-04-2024		Date of Report:	22-04-2024	Certificate No:	QC-HALL-2024-01		24-0165	5-20		
Client Name:	HALLIBURTON		Location:	HPS YARD	Job Number:	Q	QC-HALL-2024-0165				
Serial Number:	QTY	Description						Date of last thorough examination			
6022845-2-54 1884296-40 1884609-2 1884609-10 1867736-68	05	ENDLESS POLYSTER ROUND SLING FLOW LINE SAFETY RESTRAINTS MANUFACTURE: WEIR SPM EFFECTIVE LENGTH: 20 FT PN: P23625-D						28-10-2023			
Reference Standard	:	PROCEDURE	-HSE-04	HSE-0420C REV 1							
Is this the first examination after Installation or assembly at a new site or location? If the answer to the above question is YES has the equipment been installed correctly?			YES NO	✓ Within an interval of 1 With an interval of 1 In accordance with a After the occurrence circumstances?				NO NO NO NO	√ √		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE											
Is the above a defect which Is the above a defect which (If YES state the date by wh	is not y en)	et but could be					ES NO √				
Particulars of any repair, renewal or alteration required to remedy the defect identified above: Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory IS THIS EQUIPMENT SAFE TO OPERATE? YES NO											
Name of Inspector:			Name of person authenticating this report:				[6]22920 v 3 [6]				
AIZAZ FRAHT			ASHRAF ELSAID Signature & Stamp:								
Latest date by which next thorough examination must be carried out: 21-10-2024 REV: 00 Dated: 30 May 2021									45		

REV: 00 Dated: 30 May 2021

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



















