





## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch			<b>Certificate No:</b>	QC-ZPEC-05-24-0144-006
<b>Date of Examination:</b>	01-May-2024	<b>Rig &amp; Location:</b>	ZPEC Rig 25 RU-612	<b>Job Number:</b>	QC-ZPEC-May-2024-0144
<b>Serial Number:</b>	<b>QTY</b>	<b>Description:</b>		<b>SWL:</b>	<b>Date of Last Thorough Examination:</b>
L 4764	01	<b>BOW SHACKLE</b> With HEX, Bolt, Nut, And Safety Cotter Pin:  Size: 5/8" Grade: 6 Manufacture: KF Safety Factor: 6:1  Location: Rig Store: 		3.25 Ton	Nov-2023
<b>Reference Standard:</b>		BS EN 13889			
Is This The First Examination After Installation or Assembly at a New Site or Location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was The Examination Carried out: Within an Interval of 6 Months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> With an Interval of 12 Months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> In Accordance with an Examination Scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the Occurrence of Exceptional Circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the Above a Defect Which is of Immediate Danger to Persons:				YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)				YES by:	
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:					
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)					
The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:					
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>				YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>

REV: 01 Dated: 20 June 2022

<b>Inspector Name:</b>	<b>Authenticating This Report:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
Syed Aamir Ali ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEa Registered Technician		30-Nov-2024

**THIS IS TO CERTIFY THAT;** a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:

