



CERTIFICATE OF INSPECTION FOR 6 1/2" DRILL COLLAR

Client Name:	ZHONGMAN PETROLEUM AND NATURAL GAS GROUP CROP,LTD	Report No.:	ZPEC-25-QC-24-05-RS-008
Acceptance Creater:	DS-1 Fifth Edition, Volume 3 CAT 3-5	Date of Inspection:	02.MAY.2024
Work Location:	(RU-612)	Rig No.:	ZPEC-25
Test Equipment & Consumable Details			
WHITE CONTRAST WCP-2	Batch #: 220602 Manufacture: Magnaflux Exp Date: JUN,2025	TECHNICAL DETAILS	Wet Visible Continuous
BLACK INK 7HF	Batch#:220605 Manufacture: Magnaflux Exp Date: JULY.2025	COIL(1200 AMP-TURNS/IN	SC 22713 Cal.15.FEB.2024 Cal Due14.AUG.2024
FLUORESCENT 14HF	Batch #: 220306 Manufacture: Magnaflux Exp Date: March.2025	A.C HAND YOKE	201504053 Cal.15.FEB.2024 Cal Due14.AUG.2024
INTENSITY METER	SR#1608000134 CAL.Date Cal. 15.FEB.2024 Cal Due 14.AUG.2024	UV BLACK LIGHT	SR#1900084 Cal.15.FEB.2024 Cal Due14.AUG.2024
LEAD GAGE	SR#AH07KF0027 GAEMAKER LG-5003 Cal. 13.FEB.2024 Cal Due 12.AUG.2024	THREAD PROFILE GAGE	SR#21336 Cal. 13.FEB.2024 Cal Due 12.AUG.2024 SR#21335 Cal. 15.FEB.2024 Cal Due 14.AUG.2024
Magnetic Partical Concentration 7 HF	1.2 TO 2.4 ML/100 ML	WMPT Light Intensity	3500 Lux
Magnetic particle concentration flourcent 14 HF	0.1 TO 0.4 ML/100 ML	UV LIGHT INTENSITY:	2900 µw/cm ²
Magnetism Direction (Longitudinal)			
METHODOLOGY:	- Through Visual inspection - MPI inspection with Ultraviolet light - Dimensional 3		
Connection:	NC50	Size:	6 1/2"

Serial No.	Visual Inspection			MPI			Dimensional 3 Inspection																
	Pin	Box	Body				Pin						Box						Body				
				OD (in)	ID (in)	SRG $\frac{3}{4}$ (in)	SRG W $\frac{1}{2}$ (in)	Pin $\frac{3}{4}$ (in)	Bevel $\frac{1}{2}$ (in)	OD (in)	CBD $\frac{3}{4}$ (in)	CBW $\frac{1}{2}$ (in)	BB $\frac{3}{4}$ (in)	BBL $\frac{3}{4}$ (in)	Bevel $\frac{3}{4}$ (in)	Pin Tong $\frac{1}{2}$ (in)	Box Tong $\frac{3}{4}$ (in)	EGR $\frac{3}{4}$ (in)	SGR $\frac{3}{4}$ (in)	Overall $\frac{3}{4}$ (in)			
32P917	Acc.	Acc.	Acc.	Acc.	Acc.	Acc.	6 ½"	2 15/16"	23/32"	¾"	4 ½"	6 5/16"	6 ½"	5/16"	5/8"	4 5/8"	8"	6 5/16"	16 1/8"	42"	-	7/32"	-
S4212	Acc.	Acc.	Acc.	Acc.	Acc.	Acc.	6 ½"	2 15/16"	23/32"	1 1/32"	4 ½"	6 5/16"	6 ½"	5/16"	5/8"	4 5/8"	8 ¼"	6 5/16"	14 ¾"	41 ½"	-	7/32"	-
03P917	Acc.	Acc.	Acc.	Acc.	Acc.	Acc.	6 ½"	2 7/8"	23/32"	1"	4 ½"	6 5/16"	6 ½"	5/16"	5/8"	4 5/8"	8 1/8"	6 5/16"	17 7/8"	42 1/8"	-	7/32"	-
5P115	Acc.	Acc.	Acc.	Acc.	Acc.	Acc.	6 ½"	2 7/8"	23/32"	7/8"	4 ½"	6 5/16"	6 ½"	5/16"	5/8"	4 5/8"	8 1/8"	6 5/16"	15 ¾"	42 ¼"	-	7/32"	-
37P117	Acc.	Acc.	Acc.	Acc.	Acc.	Acc.	6 ½"	3"	23/32"	1"	4 ½"	6 5/16"	6 ½"	5/16"	5/8"	4 5/8"	8 1/8"	6 5/16"	14 1/8"	40 7/8"	-	7/32"	-
Conclusion:			■ 05 DRILL COLLARS above Were found "Acceptable". At the time of Inspection (Ready for Use).																				

Abbreviations :

OD	Outside Diameter	ID	Inside Diameter	SRG	Stress Relief Groove	CB	Counter Bore	BB	Bore Back	FB	Float Bore
Ø	Diameter	Ø	Length	Ø	Width	Ø	Depth	NP.	Not Present	NA.	Not Applicable
EGR	Elevator Groove Recess	SGR	Slip Groove Recess	CR	Crack	B	Bent	PC	Premium Class	RF	Reface
GT	Galled Thread	PT	Pitting Thread	SP	Seal Pitting	TD	Thread Damage	SD	Seal Damage	M	Mashed
1	100 % Coating	2	99-71 % Coating	3	70-40 % Coating	4	Up to 40 %	5	Nil	WT	Wall Thickness
Colors Code:		No Defects	Red	Crack or Extreme Damage.	Blue	Damage	Green	Seal Damage	Yellow	ACFM	

Inspector Name:	RAJESH KAILASH	Review By	
Qualification:	Senior Inspector:	Supervisor:	Customer Name:
Signature:	M.FAHAD	MOHAMED WAQAS	Customer Signature:
Original - Client Files Copy - Area Office QC/FN/AF,REP/026 Rev.00 Dated 01 AUG 2021			

