



Customer:	Daqing Drilling Company	Date Of Service:	02-05-2024
Type Of Inspection:	CAT III	Report No.:	QC-DQ-04-24-0138-33-01
Speciation:	API RP 8B	Location:	DQ RIG 1202

### AIR WINCH CAT III INSPECTION REPORT

The Rig Was Manufacture Equipped with Taian juling Exploring Equipment Co., Ltd

Equipment:	AIR WINCH
Manufacture:	Taian juling Exploring Equipment Co., Ltd
SN:	A21811
Model:	XJFH-5/25 FZP
Line Size:	5/8 in -16 mm
Total Weight:	860 KG - 1896 LBS
D.O.M:	11/2021
NEXT EXAMINATION:	After 6 Manth
PULL IN 1st LAYER:	50 KN - 11250 LBS

### PROCEDURE

- 01- Isolate the winch by shutting off the air UN wind line from the drum and inspect the line visually for any kinks, broken lines & other damages.
- 02- Remove the winch from the foundation plate or mounting brackets.
- 03- visually check all outside parts of the winch (including the spooling device and control valves) for the proper installation and damage all wear.
- 04- Performed NDT on winch connecting points to the mounting bracket or plate bolts clamps area etc. as per manufacturer recommendation.
- 05- Checked the condition & details of the manufacturer name plate.
- 06- Ensure the condition SWL is clearly marked.
- 07- Prepare and submit the inspection report.

### Inspection Results.

- \*\* Visual & MPI was carried out on the available welding and critical areas of (Air winch) components and found satisfactory for further use.
- \*\* CAT III Inspection Was Carried Out on (Air winch) and Found Accepted at The Time of Inspection.

Remarks:

Detailed reports are attached detailing all readings and results in 01 - 02 pages.

Inspector:	Mohamed Abdalla	Supervisor:	Naveed Hussien
------------	-----------------	-------------	----------------

OEM Representative	
--------------------	--





<b>Customer:</b>	Daqing Drilling Company	<b>Date Of Service:</b>	02-05-2024
<b>Type Of Inspection:</b>	CAT III	<b>Report No.:</b>	QC-DQ-04-24-0138-33-01
<b>Speciation:</b>	API RP 8B	<b>Location:</b>	DQ RIG 1202

**AIR WINCH CAT III INSPECTION REPORT**

**PROCEDURE**



**Remarks:**

Detailed reports are attached detailing all readings and results in 02 - 02 pages.



<b>Inspector:</b>	Mohamed Abdalla	<b>Supervisor:</b>	Naveed Hussien
<b>OEM Representative</b>			