Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

 $Email: OP@qualitycontrol-iraq.com\ /\ hany.akafi@qualitycontrol-iraq.com\ /\ hany.akafi@qualit$ 





#### CERTIFICATE OF THOROUGH EXAMINATION & LOAD TEST

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

This Certificate com	plies with the	requiren	nents of	the Lifting Ed	luipment Operat	tions and	d Lifting Equipi	ment Reg	gulations		
<b>Date of Examination:</b>	19-May-2024			24 Ce	rtificate No:	QC-0	5-24-004	3-001			
Client Name:	IRAQ . NAHRAIN		Lo	cation:	AL NAHRAII BASE	Job Number:		QC-I	QC-MAY-24-0043		
<b>Equipment Serial No:</b> 15		542	R	eg No:	16846 ERBI	RBIL SWL:			3500 KG		
	Model: JC	B 535-14	10		ered Hydrauli	c Systei	m JCB Fork	<u>lift.</u>			
		Chassis No#: JCB5APTGV02144943									
Description of	<b>Engine Po</b>										
Equipment	Max Capa	•									
	Manufactu										
	Year of M	_									
	Fork S/No	# <b>:</b> 82135	5 - 1850	X501							
Ref. Standard	BS ISO 233	0:2002 / I	BS ISO 5	5057:1993 / H	BS ISO 3691-1:2	015+A1	:2020				
Date of Last Examination	tte of Last Examination: June-2023 (By SCOPE) Date of Last Proof Load Test: June-2023 (By SCOPE						PE)				
Examination Type:	P	Pass Fail Notes:									
<b>Operational (No Load)</b> √   JCB Forklift Found Satisfactory For Further Use.											
Performance Test (Rated Capacity)	1 V I I R Forkliff Found to Re Acceptable to Lift 1110 % From VWI										
Proof Load Test (1.1 x Rated Capacity)		-	- Proof Load Test Shall Be Done After any Repair/ Modification								
Is This the First Examination					Was The Examina						
Installation or Assembly at a N Location?	New Site or	YE	S V		Within an Interval of 6 Months? With an Interval of 12 Months?			YES	NC		
Location:		YE	S V	NO.	In Accordance with an Examination			YES YES	√ NC		
If The Answer to The Above O Has The Equipment Been Inst		S		'	Scheme? After The Occurrence of Exceptional Circumstances?			YES	NC		
Identification of Any Part Fou	nd to Have a D	Defect Whi	ch is or C			ersons an	d a Description	of the Def	ect:		
(If None Sate NONE) NONE Is The Above a Defect Which	is of Immediat	te Danger t	o Persons	s:				/ES	NO	√	
Is The Above a Defect Which (If YES State the Date by Who	is Not Yet but				ns:	N/A					
Particulars of Any Repair, Ren						ve:					
Particulars of Any Tests Carrie In The Light of Inspection Fin Were Observed During Testin	dings Subject l	Forklift wa	s Inspect	ed Visually, O	perationally and P	erforman	ice Test was Per	formed W	here No D	efects	
IS THIS EQUIPMENT SAF							<u> </u>	YES \	NO		
Name of Inspect	or:	Name of person authenticating this Signature & Stamp:									
Aizaz Farhat		Mohamed Abdullah LEEA Registered Technician:					U G. W. II				
Date of Next Thro Examination:											
REV: 01 Dated: 20 June 2022											

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





















Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



## CERTIFICATE OF THOROUGH EXAMINATION & LOAD TEST

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	IRAQ AL NAHRAIN CO,	Location:	AL NAHRAIN CO, BASE	<b>Examination Date:</b>	19-May-2024			
<b>Equipment Serial No:</b>	1541642	REG No:	16846 ERBIL	SWL:	3500 KG			
Description of Equipment:	Diesel I	Diesel Engine Powered Hydraulic System JCB Forklift.						

No	COMPONANT CHECKS	RESULT	COMMENTS						
DAT	'A PLATE								
1	Manufacturers data plate	√							
MAS	//AST/Boom								
1	Operation	√							
2	Structure and welds	<b>√</b>							
3	Rollers & bearings	N/A							
4	Main hoist cylinder(s)	√							
5	Load chains	N/A							
6	Anchor pins	$\sqrt{}$							
7	Tilt cylinders	$\sqrt{}$							
8	Hydraulic hoses	$\sqrt{}$							
9	Side shift	$\sqrt{}$							
FOR	FORKS / JAWS								
1	Condition	√							
2	Heel wear	√							
3	Locking pins	<b>√</b>							
POV	VER PACK								
1	Operation	√							
2	Engine/motor	√							
3	Mountings	√							
4	Battery	√							
5	Wiring	$\sqrt{}$							
6	Hydraulic pump	√							
7	Isolation switches	√							
STE	ERING AND WHEELS								
1	Operation	$\sqrt{}$							
2	Steering cylinders	√							
3	Braking system	√							
4	Ball joints	V							
5	Wheel bearings	V							
6	Tire condition	V							

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





















Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

 $Email: OP@qualitycontrol-iraq.com\ /\ hany.akafi@qualitycontrol-iraq.com\ /\ hany.akafi@qualit$ 



#### CERTIFICATE OF THOROUGH EXAMINATION & LOAD TEST

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	IRAQ AL NAHRAIN CO,	Location:	AL NAHRAIN CO, BASE	<b>Examination Date:</b>	19-May-2024		
<b>Equipment Serial No:</b>	1541642	REG No:	16846 ERBIL	SWL:	3500 KG		
Description of Equipment:	Diesel Engine Powered Hydraulic System JCB Forklift.						

No	COMPONANT CHECKS	RESULT	COMMENTS						
CAI	CABIN & CONTROLS								
1	Condition	√							
2	Control levers	√							
3	Control pedals	√							
4	Internal/external lights	√							
5	Gauges	√							
6	Seat and seat belt	√							
7	Horn	√							
8	Windscreen and wipers	V							
ОТН	ER								
1	Light Alarm	√							
2	Sound Alarm	√							

#### **Key Category:**

1 = Immed	liate action	2= Action within	3= Worn/Serviceable		No Apparent Defects	N/A = Not Applicable
-----------	--------------	------------------	---------------------	--	---------------------	----------------------

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
Aizaz Farhat	Mohamed Abdullah LEEA Registered Technician:	LIE TIE	
Date of Next Through Examination:	18-May-2025	& ingmeents 2	

REV: 01 Dated: 20 June 2022

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





















Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



#### CERTIFICATE OF THOROUGH EXAMINATION & LOAD TEST

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	IRAQ AL NAHRAIN CO,	Location:	AL NAHRAIN CO, BASE	<b>Examination Date:</b>	19-May-2024	
<b>Equipment Serial No:</b>	1541642	REG No:	16846 ERBIL	SWL:	3500 KG	
Description of Equipment:	Diesel Engine Powered Hydraulic System JCB Forklift.					



























**THIS IS TO CERTIFY THAT**; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



















