



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Aberdeen Technical Service CO.			e (()	Certi	ificate No:	OC-A	TS-CER	-24-01	6-01
Date of Examination:	20.May.2024		Location: ATS YARD		Job	Number:	QC-	-ATS-CE	K-24-0	16
Equipment Serial No:		67754	1			SWL:		1000	KG	
Description of Equipment	Mobile Elevating Working Platform (Man Lift) Manufacturer Date: AICHI Date of Manufacture: 09-2002 Model: TZ20A Working Height: 22 m Platform Length: 19.7 m Platform Width: 4.4 m Max. Reach Horizontal: 11 m Chassis No: FE63EG-500074 Registration No: A 9818 BASRA									
Ref. Standard	BS EN 280:2013 + A1:2015									
Date of Last Examination:	25-Nov-	2023	Date of I	Last Proof Load	d Test:	28-N	1ay-20	22 (SCO	PE)	
Examination Type	Pass	Fail				Notes				
Operational (No Load)	٧		Elevating	Work Platform I	Found Sat	isfactory For Fur	ther Use	e.		
Performance Test (Rated Cap	acity) √		Elevating	Work Platform t	found to b	e acceptable to	lift 100	% from S	WL.	
Proof Load Test (1.1 x Rated Capacity)			Proof Lo	ad Test Shall B	e Done A	After any Repai	r/ Mod	ification		
Is this the first examination afto	Is this the first examination after Installation or assembly at a new site or location? YES NO √ Within an interval of 12 With an interval of 12 With an interval of 12			erval of 6 val of 12 r e with an e	months? months? examination scho	eme?	YES YES	NO	√ V	
equipment been installed corre	ectly?			After the occu circumstance	s?			YES	NO	
Identification of any part found NONE) NONE			ld not beco	me a danger to p	persons a	nd a description			1	
Is the above a defect which is o						1	YES		NO	√
Is the above a defect which is n (If YES state the date by when)	Is the above a defect which is not yet but could become a danger to persons (If YES state the date by whee) YES by:									
Particulars of any repair, renewal or alteration required to remedy the defect identified above:										
Particulars of any repair, renewal or alteration required to remedy the defect identified above: Particulars of any tests carried out as part of the examination: (If none state NONE) In the light of inspection findings subject Mobile Elevating Working Platform {MEWP} was Inspected visually, operationally and performance test was performed where no defects were observed during testing Hence, it was found satisfactory and fit for intended use IS THIS EQUIPMENT SAFE TO OPERATE? YES NO										

ASNT Level II Inspector Name:	Authenticating This Report:	Sign Start	Date of Next Through Examination:
Mohamed Abdalla	Ashraf El-said	Q QUALITY ONTROL	19.Nov.2024

REV: 01 Dated: 20 June 2022

























LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Aberdeen Technical Service CO.			Location:	ATS YARD
Description of Equipment:	Mobile	Mobile Elevating Working Platform (Man Lift)			677541
Date of Examination:	20.May.2024	Certificate No: QC-ATS-CER-24-016-01		SWL:	1000 KG

MEWP INSPECTION CHECKLIST

	TVIESTVI AI	SI ECTION CHECKEIS						
No	COMPONANT CHECKS	RESULT	COMMENTS					
DATA	DATA PLATE							
1	WHEELS & TYRES	$\sqrt{}$						
2	ANGLE INDICATOR	$\sqrt{}$						
3	BOOM LENGTH INDICATOR	$\sqrt{}$						
4	OPERATING LEVERS & PEDALES	$\sqrt{}$						
5	LIGHT INDICATOR & HORN	$\sqrt{}$						
6	WINDOW WIPERS & MIRROR	$\sqrt{}$						
7	INTEGRITY OF CHASSIS	$\sqrt{}$						
8	OUTRIGGERS & HOSUSING	$\sqrt{}$						
9	LEVEL INDICATORS	√						
10	LIGHTS & HORN	√						
11	HYDRULIC SYSTEM	V						
12	OPERATOR MANUAL & LOAD CHART	√						
13	SAFE LOAD INDICATOR	√						
14	PLATEFORM DECK & ACCESS	√						
15	BOOM LIFT	√						
16	WEAR PADS	√						
17	HYDRAULIC HOSES	√						
18	BOOM SECTION FOR DAMAGE	√						
19	SLEW MOTOR & GEAR	√						
20	OIL LEAKAGES OF OPERATION	√						
21	BASKET CONDITION	V						
22	GENERAL CONDITIONS	√						
23	EMERGENCY LOWERING SYSTEM	√						
* ME	E: EWP visual, function & performance test were carried out	and found accept at the time of i	inspection.					

Key Category:

1 = Immediate action	2= Action within	3= Worn/Serviceable	✓	No Apparent Defects	N/A = Not Applicable
----------------------	------------------	---------------------	----------	---------------------	----------------------

ASNT Level II Inspector Name:	Authenticating This Report:	Si natare a Stant:	Date of Next Through Examination:
Mohamed Abdalla	Ashraf El-said	Q GUALITY 10 RT NO CO	19.Nov.2024
DEV: 01 Datad: 20 Juna 2022		11.6	

REV: 01 Dated: 20 June 2022

























LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Aberdeen Technical Service CO.			Location:	ATS YARD
Description of Equipment:	Mobile	Mobile Elevating Working Platform (Man Lift)			677541
Date of Examination:	20.May.2024	Certificate No: QC-ATS-CER-24-016-01		SWL:	1000 KG

PICTORIAL

























ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stant:	Date of Next Through Examination:
Mohamed Abdalla	Ashraf El-said	Q QUALITY SONTROL	19.Nov.2024

REV: 01 Dated: 20 June 2022

























LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Aberdeen Technical Service CO.			Location:	ATS YARD
Description of Equipment:	Mobile	Mobile Elevating Working Platform (Man Lift)			677541
Date of Examination:	20.May.2024	Certificate No: QC-ATS-CER-24-016-01		SWL:	1000 KG



ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Storm:	Date of Next Through Examination:
Mohamed Abdalla	Ashraf El-said	CONTROL S	19.Nov.2024
REV: 01 Dated: 20 June 2022		11.6	



















