




CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch			Certificate No:	QC-ZPEC-05-24-0144-014
Date of Examination:	01-May-2024	Rig & Location:	ZPEC Rig 25 RU-612	Job Number:	QC-ZPEC-May-2024-0144
Serial Number:	QTY	Description:		WLL:	Date of Last Thorough Examination:
50610765	01	<p align="center"><u>CHAIN HOIST</u></p> <p>Manufacture: BASH-P Manufacture Date: May – 2015 Model: VCB177-2 Length: 3 M Safety Factor: 4:1</p> <p>Location: Rig Store:</p>		2 Ton	Nov-2023
Reference Standard:		BS EN 13157			
Is This the First Examination After Installation or Assembly at a New Site or Location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was The Examination Carried out: Within an Interval of 6 Months?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		Was The Examination Carried out: Within an Interval of 12 Months?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				In Accordance with an Examination Scheme?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				After the Occurrence of Exceptional Circumstances?	
				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the Above a Defect Which is of Immediate Danger to Persons:				<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)				YES by:	
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:					
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)					
The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/>

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Syed Aamir Ali ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEa Registered Technician		30-Nov-2024

THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:

