



ELEVATOR 5 1/2" D/P CAT IV INSPECTION REPORT

Customer:	Daqing Drilling Company	Date of inspection:	05-05-2024
Rig Name:	Rig (DQ 1202)	Report No:	QC-DQ-04-24-0138-29-02
Type of Inspection:	CAT IV Inspection.	Specification:	API RP 8B

PROCEDURE

The Rig Was Equipped with Jiangsu RYTONG PETRO Machinery Co., LTD (ELEVATOR 5" D/P)

QTY:	1 (set)	
Equipment:	ELEVATOR 5 1/2" D/P	
Product Type:	DDZ 5 1/2" EU.5IEU-350 (ton)	
SN:	230253	
Manufacture:	Jiangsu RYTONG PETRO Machinery Co., Ltd	
Date Of Manufacture:	02.2023	
SIZE:	5 1/2" EU.5IEU-350	
Ref Standard:	API RP 8B	
NEXT EXAMINATION:	After 6 Month	

Remarks:

CAT IV Inspection Was Carried Out on ELEVATOR D/P and Found Accepted at The Time of Inspection.



Inspector:

MOHAMED ABDAL

Supervisor:

NAVEED HUSSIAN

Customer Reprehensive





ELEVATOR 5 1/2" D/P CAT IV INSPECTION REPORT

Customer:	Daqing Drilling Company	Date of inspection:	05-05-2024
Rig Name:	Rig (DQ 1202)	Report No:	QC-DQ-04-24-0138-29-02
Type of Inspection:	CAT IV Inspection.	Specification:	API RP 8B

PROCEDURE

- The Products Have Been Inspected and Found Them Conformable to Relevant

The Rig was equipped with Jiangsu RUTONG PETRO Machinery Co., Ltd ELEVATOR with following specification

- ELEVATOR was found partly stripped down /assembled condition for CAT IV Inspection.

1- Visually Check for Any Damage Wear DistortionEtch.	Performed
2- Check Marking of Serial Number.	Performed
3- Clean the Weld Area from Any Rust Painting Using Grinder Brush.	Performed
4- Visual Examination for Weld Area.	Performed
5- Visual Examination for Critical Area	Performed
6- Apply White Contrast for Weld Area.	Performed
7- Apply White Contrast for Critical Area.	Performed
8- Perform MPI Using Permanent Magnet and Black Ink.	Performed
9- MPI Interpretation API RP 8B Acceptance Criteria.	Performed

PROCEDURE

** Visual And MPI Was Carried Out on The Available Welding and Critical Areas of The ELEVATOR and Found Satisfactory for Further Use.

** CAT IV Inspection Was Carried Out on ELEVATOR and Found Accepted at The Time of Inspection.

Remarks:

CAT IV Inspection Was Carried Out on ELEVATOR D/P and Found Accepted at The Time of Inspection.




Inspector: MOHAMED ABDALRAHMAN

Supervisor: NAVEED HUSSIAN

Customer Reprehensive



Customer:	Daqing Drilling Company	Date of inspection:	05-05-2024
Rig Name:	Rig (DQ 1202)	Report No:	QC-DQ-04-24-0138-29-02
Type of Inspection:	CAT IV Inspection.	Specification:	API RP 8B



DESCRIPTION	ACTUAL VALUE	OEM VALUES		RESULT
		STANDARD VALUE	MIN. VALUE	
Lifting Ear (H)	127 mm	Ø 128 mm	110 mm	ACCEPT
Hinge Pin Hole (d1)	67. mm	Ø 68 mm	Ø 62 mm	ACCEPT
Latch Pin Hole (d2)	47.18 mm	Ø 48 mm	Ø 42 mm	ACCEPT
Hinge Pin (Ø1)	67 mm	Ø 68 mm	Ø 62 mm	ACCEPT
Latch Pin (Ø2)	47 mm	Ø 48 mm	Ø 42 mm	ACCEPT

CAT IV Inspection Was Carried Out on ELEVATOR D/P and Found Accepted at The Time of Inspection.

Customer Reprehensive





ELEVATOR 5 1/2" D/P CAT IV INSPECTION REPORT

Customer:	Daqing Drilling Company	Date of inspection:	05-05-2024
Rig Name:	Rig (DQ 1202)	Report No:	QC-DQ-04-24-0138-29-02
Type of Inspection:	CAT IV Inspection.	Specification:	API RP 8B

PICTORIAL



Remarks:

CAT IV Inspection Was Carried Out on ELEVATOR D/P and Found Accepted at The Time of Inspection.



Inspector:

MOHAMED ABDAL

Supervisor:

NAVEED HUSSIEN

Customer Reprehensive

