



## Visual & Magnetic Particles Examination Report

<b>Client Name:</b>	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch:	<b>Certificate No:</b>	QC-ZPEC-05-24-0165-020
<b>Date of Examination:</b>	23-May-2024	<b>Rig &amp; Location:</b>	ZPEC Rig 25 AW-66
		<b>Job Number:</b>	QC-ZPEC-May-2024-0165
<b>Serial Number:</b>	<b>Description of the Examined Equipment:</b>		<b>Result:</b>
P249A / P249B P250A / P250B	Rig Flore Ladder Off Driller Side Connecting Pad Eye		Pass



### NDT Equipment Details:

<b>Standard:</b>	ASTM E 709	<b>Viewing Condition:</b>	Colored Media	<b>Method:</b>	WET
<b>Yoke:</b>	Permanent	<b>Serial No:</b>	PY-09	<b>Due Date:</b>	14-Aug-2024
<b>White Contrast:</b>	WCP-2	<b>Batch No:</b>	220602	<b>Due Date:</b>	June - 2025
<b>Black Ink:</b>	7HF	<b>Batch No:</b>	220605	<b>Due Date:</b>	Jan - 2025

### NDT Procedure:


Visual and MPI Carried out for The Above Description and Found Free of Surface Defects at The Time of Inspection:

Identification of any Part Found to Have a Defect and a Description of the Defect:

None

Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:

None

<b>Inspector Name:</b>	<b>Authenticating This Report:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Examination:</b>
Syed Aamir Ali ASNT Level II VT,MT,PT,UT LEEA I,II	Mohamed Abdulla LEEA Registered Technician		22-Nov-2024

REV: 01 Dated: 20 June 2022

