


CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	HALLIBURTON - HPS			Job Number:	QC-HALL-0176-07
Date of Examination:	07.May.2024	Location:	HPS	Certificate No:	QC-HALL-0176
Serial Number:	QTY	Description	SWL	Date of last thorough examination	
J6500	01	SAFETY PIN BOW SHACKLE Size: 1" Grade: 6 Manufacture: CROSBY Safety Factor: 6:1 	8.5 TON	18.Oct.2023	
Reference Standard:	BS EN 13889				
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☒ NO		Was the examination carried out: Within an interval of 6 months? ☐ YES ☒ NO With an interval of 12 months? ☐ YES ☒ NO In accordance with an examination scheme? ☐ YES ☒ NO After the occurrence of exceptional circumstances? ☐ YES ☒ NO	
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☒ NO		☐ YES ☒ NO	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				☐ YES ☒ NO	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				☐ YES ☒ NO	
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp		
Ashraf El Said	Mohamed Abdullah				
Date of Next Through Examination:	06.Nov.2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

