Al TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com





CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	16/05/2024		Date of Report:	16/05/2024		Certificate No:	QC-24-WPS-1605-010
Client Name:	HAL	LIBURTON Location:		WPS		Job Number:	160524
Serial Number:	QTY	Description			SWL	Date of manufacture if known:	Date of last thorough examination
SHEAVE-4160	1	MANUFA ENERGY S	EAVE WHEEL ASSE CTURE: HALLIBURTON SERVICES : 101007538	<u>MBLY</u>	30000 LBS	5 11/14	12/11/2023
Reference Standard: HAL DOC: ST-GL-HAL-HSE-0420							
Is this the first examination after Installation or assembly at a new site or locat If the answer to the above question is YES has equipment been installed correctly? Identification of any part found to have a defi-			he YES NO	√ With With In ac Afte circu	the examinat nin an interval n an interval o coordance with r the occurrer umstances?	YES NO √	
NONE) NONE Is the above a defect which Is the above a defect which (If YES state the date by who	mediate dar et but could	langer to persons:			·	YES NO √	
Particulars of any repair, renewal or alteration required to remedy the defect identified above: Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory							
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	
Name of Inspector:			Name of person authenticating this report:		s report: (Client Signature & Stam	
ASHRAF ELSAID			MOHAMED ABDALLAH			ALi Talib HB4890 Pate: 17/05/2024 Signature	3
Date of Next Through Ex REV: 01 Dated: 20 June 2022	ion:	15/11/2024			Taliburton	■ St. (27 Market)	

THIS IS TO CERTIFY THAT; a competent properties of the above-mentioned owner's work location on the date shown above and the equipment described in this report was texted as inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the tune of Inspection and considered Safe for Lifting.



















