




Certificate of Visual and Thorough Examination

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

| Client Name: | Honghua Oil & Gas Engineering Services Ltd. | | | Certificate No: | QC-HH-05-24-0158/10A | | |
|---|---|---|------------|-----------------|-----------------------------------|---|---|
| Date of Examination: | 15.05.2024 | Location: | HH Rig 029 | Job Number: | QC-HH-05-24-0158 | | |
| Serial Number: | QTY | Description | | SWL: | Date of last Thorough examination | | |
| M2835 | 01 | CHAIN SLING DIM:13 MM X 9.0 M Type: BOTH END PLAIN Grade: 8 Safety Factor: 4:1 Location :Air winch | | 5.3 TON | 28.01.2024 | | |
| Reference Standard: | | BS EN 818-1 | | | | | |
| Is this the first examination after Installation or assembly at a new site or location? | | YES | | NO | ✓ | Was the examination carried out: Within an interval of 6 months? | |
| | | | | | | YES | ✓ |
| | | | | | | NO | |
| If the answer to the above question is YES has the equipment been installed correctly? | | YES | | NO | | With an interval of 12 months? | |
| | | | | | | YES | ✓ |
| | | | | | | NO | ✓ |
| | | | | | | YES | ✓ |
| | | | | | | NO | |
| | | | | | | YES | ✓ |
| | | | | | | NO | |
| Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE | | | | | | | |
| Is the above a defect which is of immediate danger to persons: | | | | | | YES | |
| Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) | | | | | | NO | ✓ |
| Particulars of any repair, renewal or alteration required to remedy the defect identified above: | | | | | | YES by: | |
| Particulars of any tests carried out as part of the examination: (If none state NONE) | | | | | | | |
| The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory | | | | | | | |
| IS THIS EQUIPMENT SAFE TO OPERATE? | | | | | | YES | ✓ |
| | | | | | | NO | |

REV: 01 Dated: 20 June 2022

| | | | |
|-------------------------------|-----------------------------|--|-----------------------------------|
| ASNT Level II Inspector Name: | Authenticating This Report: | Signature & Stamp: | Date of Next Through Examination: |
| Khaled Mahmoud | Mohamed Abdullah |  | 14.11.2024 |

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

