



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS01
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
A5411	01	<u>Four Leg Wire Rope Sling</u> Diameter: 16 MM Length: 6.0 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link Assembly from Top, Connected with Safety Latch from The Bottom Hard Eye X Hard Eye Location: Store	6.3 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS02
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
A5139	01	<u>Single Leg Wire Rope Sling</u> Diameter: 36 MM Length: 8 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Soft Eye. Location : STORE	1.6 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS03
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4084 B4087 B4088 B4091 B4089 B4086 B4090 B4085	08	<u>Single Leg Wire Rope Sling</u> Diameter: 36 MM Length: 8 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Soft Eye. Location: STORE	16.6 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> With an interval of 12 months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> In accordance with an examination scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the occurrence of exceptional circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS04
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4093 B4096 B4095 B4097 B4092 B4098 B4099	07	<u>Single Leg Wire Rope Sling</u> Diameter: 36 MM Length: 6 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Soft Eye. Location: STORE	16.6 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> With an interval of 12 months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> In accordance with an examination scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the occurrence of exceptional circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS05
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4103 B4104 B4101 B4102	04	<u>Single Leg Wire Rope Sling</u> Diameter: 32 MM Length: 6 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Hard Eye. Location: STORE	13.1 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS06
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4083 B4082 B7493 B4080	04	<u>Single Leg Wire Rope Sling</u> Diameter: 44 MM Length: 6 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Soft Eye. Location: STORE	24.8 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS07
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B5930 B5931	02	<p align="center"><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 10 MM Length: 0.8 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Soft Eye.</p> <p><u>LOCATION:</u> Store</p>	1.8 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS08
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
2023YL586-1 2023YL586-2	02	<u>Single Leg Wire Rope Sling</u> Diameter: 26 MM Length: 4.1 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye. Location: Store	69 KN	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> √	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> √	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> √ <input type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS09
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4111 B4112	02	<u>Single Leg Wire Rope Sling</u> Diameter: 26 MM Length: 3.0 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye. Location: Store	8.6 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> √	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> √	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> √ <input type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS10
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4405 B4406 B4407 B4409	04	<u>Single Leg Wire Rope Sling</u> Diameter: 13 MM Length: 4.0 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Soft Eye. Location: Store	2.1 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS11
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
13121126 13121128 13121129 13121130 13121131 13121132 13121134	07	<u>Single Leg Wire Rope Sling</u> Diameter: 16 MM Length: 8 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Soft Eye. Location: Store	2.2 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> With an interval of 12 months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> In accordance with an examination scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the occurrence of exceptional circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS12
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
13121114 13121115 13121116 13121117 13121119 13121121 13121122 13121123	08	<u>Single Leg Wire Rope Sling</u> Diameter: 16 MM Length: 4 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Soft Eye. Location: Store	2.2 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/> ✓
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS13
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
13121136 13121137 13121139 13121140 13121142 13121143 13121144 13121145	09	<u>Single Leg Wire Rope Sling</u> Diameter: 16 MM Length: 5 Mss Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Soft Eye. Location: Store	2.2 Ton	N/A	13-11-2023
Reference Standard:	BS EN 13414-1/2				
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS14
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4100	01	<u>Single Leg Wire Rope Sling</u> Diameter: 36 MM Length: 3 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Soft Eye X Soft Eye. Location : Store	16.6 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS15
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F15	01	<u>Single Leg Wire Rope Sling</u> Diameter: 16 MM Length: 50 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Non Rotating Hard Eye X Plain. Location: Store	50 KN	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>	With an interval of 12 months?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
			In accordance with an examination scheme?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
			After the occurrence of exceptional circumstances?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:					YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS16
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F17	01	<u>Single Leg Wire Rope Sling</u> Diameter: 16 MM Length: 120 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Non Rotating Hard Eye X Plain. Location : Store	3.2 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>	With an interval of 12 months?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
			In accordance with an examination scheme?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
			After the occurrence of exceptional circumstances?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:					YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS17
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B1262	01	<u>Single Leg Wire Rope Sling</u> Diameter: 13 MM Length: 110 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Plain. Location: Store	10.8 KN	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> √	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/> √
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/> √
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS18
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B5130 B5131	02	<u>Single Leg Wire Rope Sling</u> Diameter: 28 MM Length: 17.98 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Soft Eye. Location : Store	10 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS19
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4116 B6662 B6661 B4119 B4120 B4121 B4114	07	<u>Two Leg Wire Rope Sling</u> Diameter: 22 MM Length: 9 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Soft Eye. <u>LOCATION:</u> Store	8.7 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> With an interval of 12 months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> In accordance with an examination scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the occurrence of exceptional circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS20
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
A5519 A3224	02	<p><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 28 MM Length: 9 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Soft Eye.</p> <p><u>LOCATION:</u> Store</p>	12.5 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS21
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
C3210 C3211	02	<p align="center"><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 22 MM Length: 8 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Soft Eye.</p> <p><u>LOCATION:</u> Store</p>	7.8 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	✓	
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO		
Was the examination carried out:					
Within an interval of 6 months?		YES	✓	NO	
With an interval of 12 months?		YES		NO	✓
In accordance with an examination scheme?		YES	✓	NO	
After the occurrence of exceptional circumstances?		YES		NO	✓
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES	NO
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	NO
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS22
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4113	01	<p align="center"><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 22 MM Length: 1.5M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Hard Eye.</p> <p><u>LOCATION:</u> Store</p>	8.7 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	✓	
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO		
Was the examination carried out:					
Within an interval of 6 months?		YES	✓	NO	
With an interval of 12 months?		YES		NO	✓
In accordance with an examination scheme?		YES	✓	NO	
After the occurrence of exceptional circumstances?		YES		NO	✓
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES	NO
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	NO
Name of Inspector:	Name of person authenticating this report:	Signature:			
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS23
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B5148 B5149	01	<p align="center"><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 38 MM Length: 2 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Hard Eye.</p> <p><u>LOCATION:</u> Store</p>	25.9 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>	With an interval of 12 months?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
			In accordance with an examination scheme?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
			After the occurrence of exceptional circumstances?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:					YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS24
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4122 B4128 B4124 B5135	04	<p align="center"><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 16 MM Length: 8 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Soft Eye.</p> <p><u>LOCATION:</u> Store</p>	4.6 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS25
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
A5137	01	<p align="center"><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 10 MM Length: 4 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Hard Eye.</p> <p><u>LOCATION:</u> Store</p>	1.6 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS26
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4125 B5134	02	<p align="center"><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 16 MM Length: 8 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Soft Eye.</p> <p><u>LOCATION:</u> Store</p>	4.6 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>	With an interval of 12 months?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
			In accordance with an examination scheme?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
			After the occurrence of exceptional circumstances?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:					YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS27
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
A5531 A5532	02	<p align="center"><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 28 MM Length: 1.2 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Hard Eye.</p> <p><u>LOCATION:</u> Store</p>	12.5 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				


REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS28
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
C3238 C3239	02	<p align="center"><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 38 MM Length: 1.7 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Hard Eye.</p> <p><u>LOCATION:</u> Store</p>	23.4 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>			
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)		YES by:			
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>			
Name of Inspector:	Name of person authenticating this report:	Signature:			
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS29
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4129 B4128 B4126 B41291	04	<u>Two Leg Wire Rope Sling</u> Diameter: 16 MM Length: 4.0 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link Assembly from Top, Connected with Bash-p Alloy Eye Hooks WLL 3 Ton with Safety Latch from The Bottom Hard Eye X Hard Eye Location: Store	4.6 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> √ <input type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS30
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B5132 B5133	02	<p align="center"><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 16 MM Length: 8 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Soft Eye.</p> <p><u>LOCATION:</u> Store</p>	4.6 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> <input type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS31
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4107 B4108 B4109 B4110	04	<u>Two Leg Wire Rope Sling</u> Diameter: 28 MM Length: 6 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Hard Eye. <u>LOCATION:</u> Store	14 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out:	
				Within an interval of 6 months?	
				Within an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS32
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4105 B4106	02	<p><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 32 MM Length: 6 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Hard Eye.</p> <p><u>LOCATION:</u> Store</p>	18.3 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out:	
				Within an interval of 6 months?	
				Within an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS33
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
CJBG2302130301 CJBG2302130302	02	<u>Single Wire Rope Sling</u> Diameter: 28 MM Length: 17.988 M Safety Factor: 5:1 EIPS, Mechanically Spliced with Open Spelter Socket at Both Ends. Location: Store	150 KN	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	✓	
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO	✓	
Was the examination carried out:		Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?			
		YES	✓	NO	✓
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE)		NONE			
Is the above a defect which is of immediate danger to persons:		YES	NO	✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)		YES by:			
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					YES
					✓
					NO
					✓
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS34
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
A5398	01	<u>Four Leg Wire Rope Sling</u> Diameter: 16 MM Length: 6.0 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Connected With Master Link Assembly From Top, Connected With Bash-p Alloy Eye Hooks WLL 3 Ton With Safety Latch From The Bottom Hard Eye X Hard Eye Location : Store	6.3 Ton	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> √ <input type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				


REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS35
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
C3226 C3228 C3229 C3230	04	<u>Two Leg Wire Rope Sling</u> Diameter: 32 MM Length: 10 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Soft Eye. <u>LOCATION:</u> Store	16.5 Ton	N/A	26-11-2023
Reference Standard:	BS EN 13414-1/2				
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		Was the examination carried out: Within an interval of 6 months? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO With an interval of 12 months? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO In accordance with an examination scheme? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO After the occurrence of exceptional circumstances? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS36
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
M1 M2	02	<p align="center"><u>Two Leg Wire Rope Sling</u></p> <p>Diameter: 22 MM First Leg Length: 6.2 M Second Leg Length: 5.2 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link. Hard Eye X Hard Eye.</p> <p>LOCATION: Store</p>	7.8 Ton	N/A	26-11-2023
Reference Standard:	BS EN 13414-1/2				
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input type="checkbox"/> √ <input type="checkbox"/> NO <input checked="" type="checkbox"/> √	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> √	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> √ <input type="checkbox"/> NO <input type="checkbox"/> √	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS37
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F12 F13	01	<p align="center"><u>Single Leg Wire Rope Sling</u></p> <p>Diameter: 16 MM Length: 1.3 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye.</p> <p><u>LOCATION:</u> SECONDARY RETENTION FALL ARRESTORE UNDER RIG FLOOR</p>	3.3 Ton	N/A	16-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> √ <input type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS38
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F07 F09	02	<u>Single Leg Wire Rope Sling</u> Diameter: 16 MM Length: 2.1 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye. <u>LOCATION:</u> MAST MANUAL TONG SECONDARY RETENTION	2.7 Ton	N/A	16-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> √ <input type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS39
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
H21	01	<p align="center"><u>Single Leg Wire Rope Sling</u></p> <p>Diameter: 14 MM Length: 1.2 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Hard Eye X Hard Eye.</p> <p><u>LOCATION:</u> SECONDARY RETENTION MAST DRILLER LINE HOLD CLAMP</p>	18 KN	N/A	16-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	✓	
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO		
		YES	NO	✓	
		YES	NO	✓	
Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?					
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons: YES NO ✓					
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) YES by:					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE? YES ✓ NO					
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS40
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F08	01	<p align="center"><u>Single Wire Rope Sling</u></p> <p>Diameter: 16 MM Length: 2.1 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Hard Eye X Hard End.</p> <p><u>LOCATION:</u> SECONDARY RETENTION MAST POWER TONG</p>	2.7 TON	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>	With an interval of 12 months?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
			In accordance with an examination scheme?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
			After the occurrence of exceptional circumstances?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:					YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS41
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F10 F11	02	<u>Single Wire Rope Sling</u> Diameter: 16 MM Length: 2.1 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Hard Eye X Hard Eye <u>LOCATION:</u> AIR WINCH SECONDARY RETENTION	2.7 TON	N/A	18-11-2023
Reference Standard:	BS EN 13414-1/2				
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input type="checkbox"/> √ <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> √ <input type="checkbox"/> NO <input type="checkbox"/> √	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				


REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS42
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F06	01	<p align="center"><u>Single Wire Rope Sling</u></p> <p>Diameter: 16 MM Length: 2.1 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Hard Eye X Hard Eye</p> <p><u>LOCATION:</u> MAN RAIDER WINCH SECONDARY RETENTION</p>	2.7 TON	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out:	
				Within an interval of 6 months?	
				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		With an interval of 12 months?	
				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
				In accordance with an examination scheme?	
				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				After the occurrence of exceptional circumstances?	
				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS43
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F03	01	<p align="center"><u>Single Wire Rope Sling</u></p> <p>Diameter: 13 MM Length: 2.1 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye</p> <p><u>LOCATION:</u> FALL ARRESTORE SECONDARY RETENTION CROWN BLOCK</p>	1.8 TON	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>	With an interval of 12 months?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
			In accordance with an examination scheme?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
			After the occurrence of exceptional circumstances?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:					YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS44
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
H17	01	<p align="center"><u>Single Wire Rope Sling</u></p> <p>Diameter: 13 MM Length: 2.1 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Hard Eye X Hard Eye</p> <p><u>LOCATION:</u> FALL ARRESTORE SECONDARY RETENTION CROWN BLOCK</p>	14 KN	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>	With an interval of 12 months?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
			In accordance with an examination scheme?		YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
			After the occurrence of exceptional circumstances?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:					YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS45
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F01	01	<p><u>Single Wire Rope Sling</u></p> <p>Diameter: 13 MM Length: 1.2 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye</p> <p><u>LOCATION:</u> CROWN BLOCK HAND RILL SECONDARY RETENTION</p>	1.8 TON	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS46
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F14	01	<p><u>Single Wire Rope Sling</u></p> <p>Diameter: 16 MM Length: 1.3 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Hard Eye X Hard Eye</p> <p><u>LOCATION:</u> SECONDARY RETENTION ROTARY HOSE</p>	3.3 TON	N/A	13-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS47
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F1 F03	02	<p align="center"><u>Single Wire Rope Sling</u></p> <p>Diameter: 10 MM Length: 1 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Hard Eye X Hard Eye</p> <p><u>LOCATION:</u> MONKEY BOARD FALLARRESTOR SECONDARY RETENTION</p>	1 TON	N/A	20-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS48
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
H19	01	<p><u>Single Wire Rope Sling</u></p> <p>Diameter: 14 MM Length: 2.1 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye</p> <p><u>LOCATION:</u> Escape Device Secondary Retention</p>	14 KN	N/A	20-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> With an interval of 12 months? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> In accordance with an examination scheme? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the occurrence of exceptional circumstances? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS49
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description		SWL	Date of manufacture if known:
F02 F04 H18	03	<u>Single Leg Wire Rope Sling</u> Diameter: 13 MM Length: 2.1 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye. Location: STORE SECONDARY RETENTION		1.8 Ton	N/A
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS50
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B5101	01	<u>Single Leg Wire Rope Sling</u> Diameter: 13 MM Length: 0.5 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye. Location: SECONDARY RETENTION STORE	2.1 Ton	N/A	25-11-2023
Reference Standard:	BS EN 13414-1/2				
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS51
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B5098 B5100	02	<u>Single Leg Wire Rope Sling</u> Diameter: 13 MM Length: 0.5 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye. Location: Power Tong Secondary Retention	2.1 Ton	N/A	25-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS52
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
T03 T04	02	<u>Single Leg Wire Rope Sling</u> Diameter: 18 MM Length: 0.8 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Soft Eye X Soft Eye. Location: Cat Walk Secondary Retention	3.8 Ton	N/A	25-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS53
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F01	01	<u>Single Leg Wire Rope Sling</u> Diameter: 10 MM Length: 1 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Hard Eye. Location: Secondary Retention Poor Boy Fall Arrestor	1 Ton	N/A	26-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS54
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B2474	01	<p><u>Man Rider Winch Single Wire Rope Sling</u></p> <p>Diameter: 10 MM Length: 110 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Non Rotating Hard Eye X Plain End.</p> <p><u>LOCATION:</u> Man Rider Winch</p>	70 KN	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> √ <input type="checkbox"/> NO <input type="checkbox"/>	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

REV: 01 Dated: 20 June 2022

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS55
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B4131 B4132	02	<u>Air Winch Single Wire Rope Sling</u> Diameter: 16 MM Length: 120 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, Non Rotating Hard Eye X Plain <u>LOCATION:</u> AIR WINCH	16.4 TON	N/A	19-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out: Within an interval of 6 months? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> With an interval of 12 months? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> In accordance with an examination scheme? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> After the occurrence of exceptional circumstances? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) <i>The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory</i>					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations



Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS56
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B1261 B1262	02	<u>Single Wire Rope Sling</u> Diameter: 10 MM Length: 110 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Plain <u>LOCATION:</u> Mast Derik Man Counter Weight	70 KN	N/A	20-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS57
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	MBL	Date of manufacture if known:	Date of last thorough examination
BB9961	01	<u>Monkey Board Air Winch Single Wire Rope Sling</u> Diameter: 10 MM Length: 25 M Safety Factor: 5:1 IWRC, Mechanically Spliced With Aluminum Ferrules, C/W Eye Hook With Safety Latch (SN:M2 , WLL:2T , 7/8"-8) Hard Eye X Plain <u>LOCATION:</u> Air Winch Monkey Board	7.5 MT	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out:	
				Within an interval of 6 months?	
				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				With an interval of 12 months?	
				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES <input type="checkbox"/> NO <input type="checkbox"/>		In accordance with an examination scheme?	
				YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				After the occurrence of exceptional circumstances?	
				YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS58
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
Z7713 Z7707	02	<u>Manual Tong Wire Rope Sling</u> Diameter: 14 MM Length: 80 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Plain End. <u>LOCATION:</u> MAST MANUAL TONG	107 KN	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS59
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
F18	01	<u>Power Tong Single Wire Rope Sling</u> Diameter: 19 MM Length: 100 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Plain End. <u>LOCATION:</u> MAST POWER TONG	4.2 TON	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> √	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/> √
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/> √
Name of Inspector:	Name of person authenticating this report:		Signature:	Stamp:	
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS60
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description		SWL	Date of manufacture if known:
2022YL10221-4 2022YL10219-10	02	<u>Cat Head Single Wire Rope Sling</u> Diameter: 26 MM Length: 9 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Hard Eye X Plan End <u>LOCATION:</u> CAT HEAD		161 KN	N/A
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS61
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
CJBG1702070101 CJBG1702070102	02	<u>Bop Hoist Wire Rope Sling</u> Diameter: 28 MM Length: 17.988 M Safety Factor: 5:1 EIPS, Mechanically Spliced with Open Spelter Socket At Both Ends. Location: Under Rig Floor	150 KN	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS62
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B6403 B6495	02	<u>Single Leg Wire Rope Sling</u> Diameter: 10 MM Length: 25 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Bash-p Alloy Eye Hooks WLL 2 Ton with Safety Latch From The Hard Eye X Plain. Location : Store	7.6 MT	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Thorough Examination:	07-11-2024				



REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	08-05-2024	Date of Report:	08-05-2024	Certificate No:	QC-DQ-04-24-0137-WS63
Client Name:	Daqing Drilling Company	Location:	Rig (DQ 1202)	Job Number:	QC-DQ-04-24-0137
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
B6658 B6659	02	<u>Two Leg Wire Rope Sling</u> Diameter: 16 MM Length: 4.0 M Safety Factor: 5:1 IWRC, Mechanically Spliced with Aluminum Ferrules, Connected with Master Link Assembly From Top, Connected With Bash-p Eye Self Looking Hooks WLL 3 Ton With The Bottom Hard Eye X Hard Eye <u>LOCATION:</u> Store	4.6 Ton	N/A	18-11-2023
Reference Standard:		BS EN 13414-1/2			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	Was the examination carried out:		<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/>
			Within an interval of 6 months?		<input type="checkbox"/> YES <input type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>	With an interval of 12 months?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/>
			In accordance with an examination scheme?		<input type="checkbox"/> YES <input type="checkbox"/> ✓ <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
			After the occurrence of exceptional circumstances?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:					<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)					YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/>
Name of Inspector:	Name of person authenticating this report:		Signature:		
Mohamed Abdalla	Ashraf Elsaid				
Date of Next Through Examination:	07-11-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

