



Visual & Magnetic Particles Examination Report

Client Name:		Black Gold Gulf Oil And Gas Services Co.Ltd Basra Iraq			Certificate No:	QC-BGG-04-24-0071-17		
Date of Examina	tion:	20.04.2024	Location:	BGG Yard	Job Number:	QC-BGG-04-24-0071		
Serial Numb	er	Description of the examined equipment						
BGGY0005-4	05-45 Drill Pipe Slips 4.5"			Result	Pass			
		ACTN 4 5300	· · · ·	oment Details				
Standard Yoke		ASTM E709 Permanent	Viewing Condition Serial No:	Colored Media PY-10	Method Due Date	WET 14.08.2024		
White Contrast		WCP-2	Batch No:	220602	Due Date	06.2025		
Black Ink		7HF	Batch No:	220602	Due Date	07.01.2025		
		/111		rocedure	Due Dale	07.01.2025		
Visual and	MDLco	rried out for the a			urface defects at	the time of inspection		
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection								
Identification of any part found to have a defect and a description of the defect: None								
Particulars of any repair, renewal or alteration required to remedy the defect identified above:								
Fai	icuidi	s of any repair, let		lone	Luy the defect lue			
L	Hone							

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:					
Abdullah Mofeed	Mohamed Abdulla	Cores -	19.10.2024					
THIS IS TO CEPTIEV THAT: a competent percendid attend the above mentioned on work location on the date chown above and the equipment								

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned over work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operation . Loting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

