Al TAKAMUL COMPANY FOR ENGINEERING TESTS
AND PROFESSIONAL SAFETY LIMITED
Basra, North Rumaila, Quality Control Yard - Iraq
Tel: +9647810009138 / +9647834964657
Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	10.05.2024	**Date of Report:**	10.05.2024	**Certificate No:**	QC-HALL-2024-0179/21
Client Name:	HALLIBURTON	**Location:**	WPS	**Job Number:**	QC-HALL-2024-0179

Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
E518	1	4 LEG WIRE ROPE SLING DIM: 3 M (L) X 19 MM (DIA) MANUFACTURER: ELMAR NOV FOS: 5:1 IWRC MECHANICALLY SPLICED WITH ALUMINUM FERRULES C/W MASTER LINK ASSEMBLEY AT THE TOP HARD EYE BOTH ENDS	9.6 T	N/A	27.05.2022
Reference Standard:	BS EN 13414-1/ HAL DOC: ST-GL-HAL-HSE-0420				

Is this the first examination after Installation or assembly at a new site or location?	YES		NO	√	Was the examination carried out:			
					Within an interval of 6 months?	YES	√	NO
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO		With an interval of 12 months?	YES		NO √
					In accordance with an examination scheme?	YES	√	NO
					After the occurrence of exceptional circumstances?	YES		NO √

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE				
Is the above a defect which is of immediate danger to persons:	YES		NO	√
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)	N/A			
Particulars of any repair, renewal or alteration required to remedy the defect identified above:				
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory				
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:
Ashraf Elsaid	Aizaz Farhat	ALI Talib HB48903 Date: 11-05-2024 Signature Haliburton
Date of Next Through Examination:	09/11/2024	

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.