

AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq




CERTIFICATE OF QUALIFICATION VISUAL INSPECTION AND LEAK TESTING

THIS REPORT COMPLIES WITH RECOGNIZED INTERNATIONAL STANDARDS & TECHNICAL REQUIREMENTS

CLIENT:	HALLIBURTON (HPS)		
LOCATION:	HPS YARD	REPORT No.:	QC-24-HALL-HPS-VT & LEAK -001
STANDARD:	CUSTOMER SPECIFICATION	JOB NO:	QC-24/HALL-HPS-007
INSPECTION DATE:	Saturday, August 10, 2024	Due Date	Sunday, February 9, 2025
TYPE OF INSPECTION:	*VISUAL TESTING AND *LEAK TESTING		
DESCRIPTION:	FRAC TANK	SAP NO:	11876159
MEDIUM USED:	WATER	HOLDING TIME:	15 MINUTES

PICTURES



INSPECTION RESULT

VISUAL TESTING:	Visual Testing of Frac Tank did not found Deforms Mechanical Damage, Cracks and Corrosion. At time of Inspection.
LEAK TESTING:	Leak Testing of Frac Tank did not found any leakage during the holding time. At time of Inspection.

Inspection Evaluation

VISUAL TESTING-The above mentioned Frac Tank was found "Satisfactory" Fit for intended used.

LEAK TESTING- The above mentioned Frac Tank was found "Satisfactory" Fit for intended used.

PERSONNEL DETAILS			REVIEW BY		
NAME:	M.SHAHZAD AHMED		SENIOR INSPECTOR:	NAVEED HUSSAIN	CUSTOMER NAME
QUALIFICATION:	ASNT LEVEL II MT,PT,VT		SUPERVISOR:	HANI ALI	
STAMP & SIGNATURE:			DATE:		

Original - Client Files Copy - Area Office QC/FN/MPI/065 Rev.00 DATED 07 NOV 2021



Tel: +9647810009138 / +9647834964657
Email: OP@qualitycontrol-iraq.com
hany.akafi@qualitycontrol-iraq.com