



Customer:	Daqing Drilling Company	Date Of Service:	04-05-2024
Type Of Inspection:	CAT III	Report No.:	QC-DQ-04-24-0138-21-01
Speciation:	ASME 709	Location:	DQ RIG 1202

CAT HEAD CAT III INSPECTION REPORT

Marker & Date of Manufacture: China Petroleum Liaohe Equipment Company / 11-2020 Model: YM16-II Flow Rated: 120 L/min Pull Stroke: 1.5 M Pressure: 16 mpa – 2320 psi Pull: 160 KN Pull Speed: 9 M/Min	<u> </u>	AT HEAD CAT III INSPECTION REPORT				
SN: YM2020007, YM2020008 Marker & Date of Manufacture: China Petroleum Liaohe Equipment Company / 11-2020 Model: YM16-II Flow Rated: 120 L/min Pull Stroke: 1.5 M Pressure: 16 mpa – 2320 psi Pull: 160 KN Pull Speed: 9 M/Min NEXT EXAMINATION: After 6 Manth PROCEDURE 01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visuall & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use.						
SN: VM2020007, YM2020008 Marker & Date of Manufacture: China Petroleum Liaohe Equipment Company / 11-2020 Model: VM16-II Flow Rated: 120 L/min Pull Stroke: 1.5 M Pressure: 16 mpa – 2320 psi Pull: 160 kN Pull Speed: 9 M/Min NEXT EXAMINATION: After 6 Manth PROCEDURE 01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use.	Equipment:	Cat Head				
Marker & Date of Manufacture: Model: YM16-II Flow Rated: 120 L/min Pull Stroke: 1.5 M Pressure: 16 mpa – 2320 psi Pull: 160 KN Pull Speed: 9 M/Min NEXT EXAMINATION: After 6 Manth PROCEDURE 01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use.	SN:	distribution of the control of the c				
Model: YM16-II Flow Rated: 120 L/min Pull Stroke: 1.5 M Pressure: 16 mpa – 2320 psi Pull: 160 KN Pull Speed: 9 M/Min NEXT EXAMINATION: After 6 Manth PROCEDURE 01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visuall & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use.						
Pull: 1.5 M Pressure: 1.6 mpa - 2320 psi Pull: 1.60 KN Pull Speed: 9 M/Min NEXT EXAMINATION: After 6 Manth PROCEDURE 01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.	Model:					
Pull: 160 KN Pressure: 16 mpa - 2320 psi Pull: 160 KN PUII Speed: 9 M/Min NEXT EXAMINATION: After 6 Manth PROCEDURE 01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.	Flow Rated :	120 L/min				
Pull Speed: 9 M/Min NEXT EXAMINATION: After 6 Manth PROCEDURE 01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: thatled reports are attached detailing all readings and results in 01 - 04 pages.	Pull Stroke:					
Pull Speed: 9 M/Min NEXT EXAMINATION: After 6 Manth PROCEDURE 01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: thatled reports are attached detailing all readings and results in 01 - 04 pages.	Pressure:	16 mpa – 2320 psi				
PROCEDURE 01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.	Pull:					
PROCEDURE 01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.	Pull Speed :	9 M/Min				
01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.	NEXT EXAMINATION:					
01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.						
01- Visually checked for the serial number. 02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.		PROCEDURE				
02- Cathead Buffing & Cleaning Done as per the requirements of qualified inspector. 03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.	01- Visually checked for					
03- Visually checked for damage, deformations or cracks. 04- Visual & MPI checked for whole Cathead. 05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.						
05- Checked for the measure hole & checked the shaft. 06- Down grade the Cathead as necessary according to the measured wear to the maximum Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.						
Inspection Results. ** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.	04- Visual & MPI checke	ed for whole Cathead.				
** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. **marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.	05- Checked for the mea	asure hole & checked the shaft.				
** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.	06- Down grade the Cat	head as necessary according to the measured wear to the maximum				
** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.						
** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.						
** Visual & MPI was carried out on the available critical areas of the Cathead and found Accept at the time of inspection ** CAT III Inspection was carried out on Cathead & found satisfactory for further use. marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.						
** CAT III Inspection was carried out on Cathead & found satisfactory for further use. **marks: **tailed reports are attached detailing all readings and results in 01 - 04 pages.		Inspection Results.				
** CAT III Inspection was carried out on Cathead & found satisfactory for further use. **marks: **tailed reports are attached detailing all readings and results in 01 - 04 pages.	** Visual & MPI v					
** CAT III Inspection was carried out on Cathead & found satisfactory for further use. **marks: **tailed reports are attached detailing all readings and results in 01 - 04 pages.						
marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.						
marks: tailed reports are attached detailing all readings and results in 01 - 04 pages.	** CAT III Inspection	was carried out on Cathood & found satisfactory for further use				
tailed reports are attached detailing all readings and results in 01 - 04 pages.	CAI III IIIspection	was carried out on Catheau & Joung Satisfactory for further use.				
tailed reports are attached detailing all readings and results in 01 - 04 pages.						
tailed reports are attached detailing all readings and results in 01 - 04 pages.						
tailed reports are attached detailing all readings and results in 01 - 04 pages.						
tailed reports are attached detailing all readings and results in 01 - 04 pages.						
tailed reports are attached detailing all readings and results in 01 - 04 pages.						
tailed reports are attached detailing all readings and results in 01 - 04 pages.						
		4. :1:				
Avamul Corps	etatiea reports are attached de	etailing all readings and results in VI - V4 pages.				
akamul Conga						
akamul Cons						
		Vamul Cons				

Inspector: Mohamed Abdullah Operation Manger: Ashraf Alsaid

OEM Representative





Customer:	Daqing Drilling Company	Date Of Service:	04-05-2024
Type Of Inspection:	CAT III	Report No.:	QC-DQ-04-24-0138-21-01
Speciation:	ASME 709	Location:	DQ RIG 1202

CAT HEAD CAT III INSPECTION REPORT



























Remarks:

Detailed reports are attached detailing all readings and results in 02 - 04 pages.

Inspector: Mohamed Abdullah Operation Manger: Ashraf Alsaid

OEM Representative





Customer:	Daqing Drilling Company	Date Of Service:	04-05-2024
Type Of Inspection:	CAT III	Report No.:	QC-DQ-04-24-0138-21-01
Speciation:	ASME 709	Location:	DQ RIG 1202

CAT HEAD CAT III INSPECTION REPORT

PROCEDURE

























<u>:Remarks</u>

Detailed reports are attached detailing all readings and results in 03 - 04 pages.

wamul Copy

		NDT E		
Inspector:	Mohamed Abdullah		Operation Manger:	Ashraf Alsaid
OEM Popros	ontativo	The state of the s		





Customer:	Daqing Drilling Company	Date Of Service:	04-05-2024
Type Of Inspection:	CAT III	Report No.:	QC-DQ-04-24-0138-21-01
Speciation:	ASME 709	Location:	DQ RIG 1202

CAT HEAD CAT III INSPECTION REPORT

PROCEDURE















	Nominal		Groove depth (mm)			
No	Sheaves S/N	Wire Did (d) mm	Actual	Min. 1.33 * d	Max. 1.75 * d	Result
01	YM2020007-1	28	41.19	37.24 MM	49 MM	Pass
						+
02	YM2020007-2		41.23	37.24 MM	49 MM	Pass
03	YM2020008-1	28	41.24	37.24 MM	49 MM	Pass
04	YM2020008-2	28	41.22	37.24 MM	49 MM	Pass

<u>Remarks:</u>
Detailed reports are attached detailing all readings and results in 04 - 04 pages.

Wamul Con

		NDT E		
Inspector:	Mohamed Abdullah		Operation Manger:	Ashraf Alsaid
OEM Represe	entative	The state of the s		