

Al TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:		Aberdeen Techni Services	cal Rig & Location:	Aberdeen Ya	erdeen Yard C		No:	QC-ATS-0074-001			
Examination Date:		23-Apr-2024 Due Date: 22-Oct-2024			4 J	Job Numb	QC-ATS-Apr-2024- 0074				
Serial Number:	QTY:		Item Description:		SWL:		Date of Manufacture:		Date of Last Thorough Examination		
C 01 C 02 C 03 C 04	04	Locati	Collared Eyebolt Thread Size: 24mm (M24) Eyebolt Eye Diameter: 50mm Eyebolt Eye thickness: 20mm Location: Automatic Fire Fighting System:				Nil Nil				
Reference Standard: BS EN: ISO 3266 ASME: B18/B30 DIN: 580-2017											
* *			YES √ NO	With an interval of 12 mc			YES YES		√	NO	
NONE) NONE Is the above a defect that is of immediate danger							Y	ES	N	O \	
Is the above a defect t (If YES state the date	by when)		ome a danger to persons quired to remedy the defect identified above:			N/A					
The subject Item	ns were in	Particulars of any spected Visually ar	tests carried out as part ad dimensionally where satisfa	of the examination no signs of defects	n: (If none	e state NONI erved at the	E) time of i	inspectio	n and fo	und	
IS THIS EQUIPME	NT SAFE	1				. 0.4		ES	N	O	
Name of Inspector:		r: Nam	Name of person authenticating this report:		Sign	compan					
Ashraf El Said			M Abdullah								
CERTIFICATION ASNT LEVEL II VT,MT,PT,UT,RT, LEEA I,II,					A	S S S S S S S S S S S S S S S S S S S					
REV: 01 Dated: 20 June	2022				~	er Engin	eet				

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





















