





CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-001
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number: QC-ATS-May-2024-0081
Serial Number:	QTY	Description:	SWL:	Date of Last Thorough Examination:
D215-1503 D215-1506 D215-1510 D215-1511	04	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 06-Oct-2016 Material: 100% Polyester (PET) Length: 6 M Width: 2 in Color: Green Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 	Vertical 2 Ton	11-Nov-2023
Reference Standard:	BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	√	Was The Examination Carried out: Within an Interval of 6 Months? YES √ NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	With an Interval of 12 Months? YES NO √
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances? YES √ NO			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES	NO	√	YES by:
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)	Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)	Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:			
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-002
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number: QC-ATS-May-2024-0081
Serial Number:	QTY	Description:	SWL:	Date of Last Thorough Examination:
D215-1525 D215-1526 D215-1529 D215-1530 D215-1532 D215-1533 D215-1534	07	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 06-Oct-2016 Material: 100% Polyester (PET) Length: 8 M Width: 2 in Color: Green Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 	Vertical 2 Ton	11-Nov-2023
Reference Standard:	BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	√	Was The Examination Carried out: Within an Interval of 6 Months? YES √ NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	With an Interval of 12 Months? YES NO √
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE	NONE			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES	NO	√	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances? YES √ NO
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)				YES by:
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:				
Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:				
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Lea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-003
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number: QC-ATS-May-2024-0081
Serial Number:	QTY	Description:	SWL:	Date of Last Thorough Examination:
D215-1516	01	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 06-Oct-2016 Material: 100% Polyester (PET) Length: 10 M Width: 2 in Color: Green Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 	Vertical 2 Ton	11-Nov-2023
Reference Standard:	BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	YES	NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	YES	NO
Was The Examination Carried out: Within an Interval of 6 Months?		YES	NO	
Within an Interval of 12 Months?		YES	NO	
In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances?		YES	NO	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE				
Is the Above a Defect Which is of Immediate Danger to Persons:		YES	NO	
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)		YES by:		
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:				
Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:				
IS THIS EQUIPMENT SAFE TO OPERATE?		YES	NO	

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-004
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number: QC-ATS-May-2024-0081
Serial Number:	QTY	Description:	SWL:	Date of Last Thorough Examination:
D31705263	01	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 14-May-2017 Material: 100% Polyester (PET) Length: 5 M Width: 3 in Color: Yellow Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 	Vertical 3 Ton	11-Nov-2023
Reference Standard:	BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	√	Was The Examination Carried out: Within an Interval of 6 Months? YES √ NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	With an Interval of 12 Months? YES NO √
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances? YES √ NO			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES	NO	√	YES by:
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)	Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)	Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:			
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-005
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number: QC-ATS-May-2024-0081
Serial Number:	QTY	Description:	SWL:	Date of Last Thorough Examination:
D317-477	01	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 20-Feb-2017 Material: 100% Polyester (PET) Length: 8 M Width: 3 in Color: Yellow Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 	Vertical 3 Ton	11-Nov-2023
Reference Standard:	BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	√	Was The Examination Carried out: Within an Interval of 6 Months? YES √ NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	With an Interval of 12 Months? YES NO √
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances? YES √ NO			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES	NO	√	YES by:
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)	Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)	Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:			
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-006
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number: QC-ATS-May-2024-0081
Serial Number:	QTY	Description:	SWL:	Date of Last Thorough Examination:
D517-039	01	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 20-Feb-2017 Material: 100% Polyester (PET) Length: 5 M Width: 5 in Color: Red Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 	Vertical 5 Ton	11-Nov-2023
Reference Standard:	BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	√	Was The Examination Carried out: Within an Interval of 6 Months? YES √ NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	With an Interval of 12 Months? YES NO √
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances? YES √ NO			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES	NO	√	YES by:
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)	Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)	Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:			
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-007	
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number:	QC-ATS-May-2024-0081
Serial Number:	QTY	Description:		SWL:	Date of Last Thorough Examination:
D5170265	01	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 14-Feb-2017 Material: 100% Polyester (PET) Length: 10 M Width: 5 in Color: Red Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 		Vertical 5 Ton	11-Nov-2023
Reference Standard:		BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?		YES	NO	Was The Examination Carried out: Within an Interval of 6 Months?	
			✓	YES	NO
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO	Was The Examination Carried out: Within an Interval of 12 Months?	
		✓		YES	NO
				In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances?	
				YES	NO
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the Above a Defect Which is of Immediate Danger to Persons:			YES	NO	✓
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)			YES by:		
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:					
Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:					
IS THIS EQUIPMENT SAFE TO OPERATE?			YES	NO	✓

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-008
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number: QC-ATS-May-2024-0081
Serial Number:	QTY	Description:	SWL:	Date of Last Thorough Examination:
D615-944 D615-045	02	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 06-Oct-2016 Material: 100% Polyester (PET) Length: 2 M Width: 6 in Color: Brown Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 	Vertical 6 Ton	11-Nov-2023
Reference Standard:	BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	√	Was The Examination Carried out: Within an Interval of 6 Months? YES √ NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	With an Interval of 12 Months? YES NO √
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances? YES √ NO			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES	NO	√	YES by:
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)	Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:			
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:	IS THIS EQUIPMENT SAFE TO OPERATE? YES √ NO			

REV: 01 Dated: 20 June 2022


Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024

THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:




CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-009
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number: QC-ATS-May-2024-0081
Serial Number:	QTY	Description:	SWL:	Date of Last Thorough Examination:
D6170202 D6170203 D6170205 D6170207 D6170208 D6170209 D6170215 D6170218	08	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 14-Feb-2017 Material: 100% Polyester (PET) Length: 4 M Width: 6 in Color: Brown Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 	Vertical 6 Ton	11-Nov-2023
Reference Standard:	BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	√	Was The Examination Carried out: Within an Interval of 6 Months? YES √ NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	With an Interval of 12 Months? YES NO √
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances? YES √ NO			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES	NO	√	YES by:
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)	Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)	Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:			
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Lea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:			Certificate No:	QC-ATS-05-24-0081-010
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number:	QC-ATS-May-2024-0081
Serial Number:	QTY	Description:		SWL:	Date of Last Thorough Examination:
D617-314 D617-315	02	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 20-Feb-2017 Material: 100% Polyester (PET) Length: 10 M Width: 6 in Color: Brown Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 		Vertical 6 Ton	11-Nov-2023
Reference Standard:		BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was The Examination Carried out: Within an Interval of 6 Months? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		With an Interval of 12 Months? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
				In Accordance with an Examination Scheme? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				After the Occurrence of Exceptional Circumstances? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the Above a Defect Which is of Immediate Danger to Persons:				<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)				YES by:	
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:					
Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/>

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024

THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-011	
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number:	QC-ATS-May-2024-0081
Serial Number:	QTY	Description:		SWL:	Date of Last Thorough Examination:
D8170201 D8170206	02	<p style="text-align: center;"><u>FLAT POLYESTER WOVEN WEBBING SLING</u></p> <p style="text-align: center;">C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 14-Feb-2017 Material: 100% Polyester (PET) Length: 3 M Width: 8 in Color: Blue Safety Factor: 7:1</p> <p>Location: ATS Yard:</p>		Vertical 8 Ton	11-Nov-2023
Reference Standard:		BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was The Examination Carried out:	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		<input type="checkbox"/> Within an Interval of 6 Months? <input type="checkbox"/> Within an Interval of 12 Months? <input type="checkbox"/> In Accordance with an Examination Scheme? <input type="checkbox"/> After the Occurrence of Exceptional Circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE					
Is the Above a Defect Which is of Immediate Danger to Persons:		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		YES by:	
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)					
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:					
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)					
The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:					
IS THIS EQUIPMENT SAFE TO OPERATE?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>			

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024

THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:	Certificate No:	QC-ATS-05-24-0081-012		
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number:	QC-ATS-May-2024-0081
Serial Number:	QTY	Description:		SWL:	Date of Last Thorough Examination:
D81705209 D81705204 D81705212	03	<p style="text-align: center;"><u>FLAT POLYESTER WOVEN WEBBING SLING</u></p> <p style="text-align: center;">C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 14-May-2017 Material: 100% Polyester (PET) Length: 4 M Width: 8 in Color: Blue Safety Factor: 7:1</p> <p>Location: ATS Yard:</p>		Vertical 8 Ton	11-Nov-2023
Reference Standard:		BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was The Examination Carried out: Within an Interval of 6 Months?	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				Was The Examination Carried out: Within an Interval of 12 Months?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances?	
				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE					
Is the Above a Defect Which is of Immediate Danger to Persons:				<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)				YES by:	
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:					
Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/>

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:	Certificate No:	QC-ATS-05-24-0081-013		
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number:	QC-ATS-May-2024-0081
Serial Number:	QTY	Description:		SWL:	Date of Last Thorough Examination:
D815-151	01	<p style="text-align: center;"><u>FLAT POLYESTER WOVEN WEBBING SLING</u></p> <p style="text-align: center;">C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 16-Oct-2017 Material: 100% Polyester (PET) Length: 4 M Width: 8 in Color: Blue Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 		Vertical 8 Ton	11-Nov-2023
Reference Standard:		BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was The Examination Carried out:	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE					
Is the Above a Defect Which is of Immediate Danger to Persons:				YES	<input type="checkbox"/>
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)				YES by:	
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:					
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)					
The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	<input checked="" type="checkbox"/>
				NO	<input type="checkbox"/>

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024

THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-014	
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number:	QC-ATS-May-2024-0081
Serial Number:	QTY	Description:		SWL:	Date of Last Thorough Examination:
D81804095 D81804098	02	<p style="text-align: center;"><u>FLAT POLYESTER WOVEN WEBBING SLING</u></p> <p style="text-align: center;">C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 30-Sep-2018 Material: 100% Polyester (PET) Length: 6 M Width: 8 in Color: Blue Safety Factor: 7:1</p> <p>Location: ATS Yard:</p>		Vertical 8 Ton	11-Nov-2023
Reference Standard:		BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was The Examination Carried out:	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE					
Is the Above a Defect Which is of Immediate Danger to Persons:				<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)				YES by:	
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:					
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)					
The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-015
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number: QC-ATS-May-2024-0081
Serial Number:	QTY	Description:	SWL:	Date of Last Thorough Examination:
D1015-318	01	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 06-Oct-2016 Material: 100% Polyester (PET) Length: 4 M Width: 10 in Color: Orange Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 	Vertical 10 Ton	11-Nov-2023
Reference Standard:	BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	√	Was The Examination Carried out: Within an Interval of 6 Months? YES √ NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	With an Interval of 12 Months? YES NO √
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances? YES √ NO			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES	NO	√	YES by:
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)	Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)	Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:			
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

REV: 01 Dated: 20 June 2022


Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024

THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:




CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-016	
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number:	QC-ATS-May-2024-0081
Serial Number:	QTY	Description:		SWL:	Date of Last Thorough Examination:
D1017-030	01	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 20-Feb-2017 Material: 100% Polyester (PET) Length: 8 M Width: 10 in Color: Orange Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 		Vertical 10 Ton	11-Nov-2023
Reference Standard:		BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?		YES	NO	Was The Examination Carried out: Within an Interval of 6 Months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO	With an Interval of 12 Months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
				In Accordance with an Examination Scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				After the Occurrence of Exceptional Circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the Above a Defect Which is of Immediate Danger to Persons:			YES	NO	<input checked="" type="checkbox"/>
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)			YES by:		
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:					
Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:					
IS THIS EQUIPMENT SAFE TO OPERATE?			YES	<input checked="" type="checkbox"/>	NO <input type="checkbox"/>

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-017
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number: QC-ATS-May-2024-0081
Serial Number:	QTY	Description:	SWL:	Date of Last Thorough Examination:
D81705206	01	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 14-May-2017 Material: 100% Polyester (PET) Length: 4 M Width: 8 in Color: Blue Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 	Vertical 8 Ton	11-Nov-2023
Reference Standard:	BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	√	Was The Examination Carried out: Within an Interval of 6 Months? YES √ NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	With an Interval of 12 Months? YES NO √
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances? YES √ NO			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES	NO	√	YES by:
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)	Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)	Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:			
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024


THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN TECHNICAL SECVICE CO:		Certificate No:	QC-ATS-05-24-0081-018
Date of Examination:	05-May-2024	Location:	ATS Yard	Job Number: QC-ATS-May-2024-0081
Serial Number:	QTY	Description:	SWL:	Date of Last Thorough Examination:
D815-153 D815-158	02	<p><u>FLAT POLYESTER WOVEN WEBBING SLING</u> C/W Folded Soft Eye at Each End</p> <p>Manufacture: Webblon Korea: Manufacture Date: 06-Oct-2016 Material: 100% Polyester (PET) Length: 4 M Width: 8 in Color: Blue Safety Factor: 7:1</p> <p>Location: ATS Yard:</p> 	Vertical 8 Ton	11-Nov-2023
Reference Standard:	BS EN 1492-1:2000-A1:2008			
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES	NO	√	Was The Examination Carried out: Within an Interval of 6 Months? YES √ NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	√	NO	With an Interval of 12 Months? YES NO √
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none Sate NONE) NONE	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances? YES √ NO			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES	NO	√	YES by:
Is the Above a Affect Which is not yet but Could Become a Danger to Persons (If YES State The Date by When)	Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE)	Particulars of any tests Carried out as Part of the Examination: (If none state NONE) The Subject Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection and Found Satisfactory:			
IS THIS EQUIPMENT SAFE TO OPERATE?	YES	√	NO	

REV: 01 Dated: 20 June 2022

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Ashraf El Said ASNT Level II VT,MT,PT,UT Leea I,II	Mohamed Abdulla LEEA Registered Technician		04-Nov-2024

THIS IS TO CERTIFY THAT; a Competent Person Did Attend the Above-Mentioned Owner's Work Location on the Date Shown Above and the Equipment Described in this Report was Tested & Inspected as per the Requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The Result was Found Satisfactory at the Time of Inspection and Considered Safe for Lifting:

