Al TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647834966105 / +9647834964657

Email: ashraf.said@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com

CERTIFICATE OF THOROUGH EXAMINATION

QUALIT

ONTRO

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:		08/06/2024		Date of Report:	08/06/202	08/06/2024		Certificate No:		QC-24-WPS-0806-005		
Client Name:		HALLIBURTON		Location:	WPS	WPS		Job Number:		080624		
Serial Number:	QTY	Description				SWL		Date of manufacture if known:		Date of last thorough examination		
		4	LEGS	S WIRE ROPE								
C452	1	-	CHANI CHANI COMU	TH ALUMINUM MBLY FROM	4.4 T		N/A		06/03/2024			
Reference Standard: BS EN 13414-1/ HAL DOC: ST-GL-HAL-HSE-0420												
Is this the first examination after Installation or assembly at a new site or loc If the answer to the above question is YES I equipment been installed correctly?			as the	YES NO	 Was the examination carried out: ✓ Within an interval of 6 months? With an interval of 12 months? In accordance with an examination sche After the occurrence of exceptional circumstances? 				YE	ES √ ES √	NO NO NO	√
NONE) NONE	int iound	to have a de	elect wh	lich is of could not be	come a danger to j	persons	anu a ue	escription of the	e dere	ect: (ii n	one sat	.e
Is the above a defect which is of immediate dar								Y	/ES		NO	\checkmark
Is the above a defect which is not yet but could be (If VES state the date by when)				ome a danger to persons			N/A					
(If YES state the date by when) Particulars of any repair, renewal or alteration required to remedy the defect identified above:												
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory IS THIS EQUIPMENT SAFE TO OPERATE? YES √ NO												
IS THIS EQUILIBERT SATE TO OF ERATE:									LJ			
Name of Inspector:				Name of person authenticating this report:			Client Signature & Stamp:				щQ	
ASHRAF ELSAID			MOHAMED ABDALLAH			ALi Talib HB48903 Date: 09/06/2024						
Date of Next Through Examination:			07/12/2024			Signature Haliburton			-			
REV: 01 Dated: 20 June 20	22		LIF									

THIS IS TO CERTIFY THAT; a competent persol did attactive prove-mentioned owner's work location on the date shown above and the equipment described in this report wall tester as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



