




CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/53		
Serial Number	Description of the examined equipment		Result
G01	MUD SYSTEM GRATING (Lifting Point)		Pass



NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION


Client Name:	Hong Hua Oil & Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/54		
Serial Number	Description of the examined equipment		Result
G02	MUD SYSTEM GRATING (Lifting Point)		Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil & Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
		Certificate No:	QC-HH-06-24-0175-01/55


Serial Number	Description of the examined equipment	Result
G03	MUD SYSTEM GRATING (Lifting Point)	Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil & Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/56		
Serial Number	Description of the examined equipment		Result
G04	MUD SYSTEM GRATING (Lifting Point)		Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
		Certificate No:	QC-HH-06-24-0175-01/57


Serial Number	Description of the examined equipment	Result
G05	MUD SYSTEM GRATING (Lifting Point)	Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION


Client Name:	Hong Hua Oil & Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/58		
Serial Number	Description of the examined equipment		Result
G06	MUD SYSTEM GRATING (Lifting Point)		Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024



THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/59		
Serial Number	Description of the examined equipment		Result
G07	MUD SYSTEM GRATING (Lifting Point)		Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/60		
Serial Number	Description of the examined equipment		Result
G08	MUD SYSTEM GRATING (Lifting Point)		Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/61		
Serial Number	Description of the examined equipment		Result
G09	MUD SYSTEM GRATING (Lifting Point)		Pass




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION


Client Name:	Hong Hua Oil & Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/62		
Serial Number	Description of the examined equipment		Result
G10	MUD SYSTEM GRATING (Lifting Point)		Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil & Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
		Certificate No:	QC-HH-06-24-0175-01/63


Serial Number	Description of the examined equipment	Result
G11	MUD SYSTEM GRATING (Lifting Point)	Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION


Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/64		
Serial Number	Description of the examined equipment		Result
G12	MUD SYSTEM GRATING (Lifting Point)		Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
		Certificate No:	QC-HH-06-24-0175-01/65


Serial Number	Description of the examined equipment	Result
G13	MUD SYSTEM GRATING (Lifting Point)	Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.








CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil & Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
		Certificate No:	QC-HH-06-24-0175-01/66

Serial Number	Description of the examined equipment	Result
G14	MUD SYSTEM GRATING (Lifting Point)	Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/67		
Serial Number	Description of the examined equipment		Result
G15	MUD SYSTEM GRATING (Lifting Point)		Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION


Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/68		
Serial Number	Description of the examined equipment		Result
G16	MUD SYSTEM GRATING (Lifting Point)		Pass



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure	
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection	
Identification of any part found to have a defect and a description of the defect:	
None	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:	
None	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





CERTIFICATION OF Visual, THOROUGH EXAMINATION & MAGNETIC PARTICLE INSPECTION

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-06-24-0175
Date of Examination:	06.06.2024	Location:	HH Rig 029
Certificate No:	QC-HH-06-24-0175-01/69		
Serial Number	Description of the examined equipment		Result
G17	MUD SYSTEM GRATING (Lifting Point)		Pass




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

