

AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq



CERTIFICATE OF QUALIFICATION VISUAL INSPECTION AND LEAK TESTING

THIS REPORT COMPLIES WITH RECOGNIZED INTERNATIONAL STANDARDS & TECHNICAL REQUIREMENTS

CLIENT:	HALLIBURTON (WPS)		
LOCATION:	WPS YARD	REPORT No.:	QC-24-HALL-WPS-VT & LEAK -002
STANDARD:	CUSOMER SPECIFICATION	JOB NO:	80624
INSPECTION DATE:	Saturday, June 8, 2024	Due Date	Saturday, December 7, 2024
TYPE OF INSPECTION:	*VISUAL TESTING AND *LEAK TESTING		
DESCRIPTION:	TANK	SR NO:	AW-TK-001
MEDIUM USED:	WATER	HOLDING TIME:	15 MINUTES

PICTURES



INSPECTION RESULT

VISUAL TESTING:	Visual Testing of Tank did not found Deforms Mechanical Damage, Cracks and Corrosion. At time of Inspection.
LEAK TESTING:	Leak Testing of Tank did not found any leakage during the holding time. At time of Inspection.

Inspection Evaluation

VISUAL TESTING-The above mentioned Tank was found "Satisfactory" Fit for intended used.

LEAK TESTING- The above mentioned Tank was found "Satisfactory" Fit for intended used.

PERSONNEL DETAILS			REVIEW BY		
NAME:	M.SHAHZAD AHMED		SENIOR INSPECTOR:	NAVEED HUSSAIN	CUSTOMER NAME
QUALIFICATION:	ASNT LEVEL II MT,PT,VT		SUPERVISOR:	HANI ALI	ALI Talib HB48903 Date: 09/06/2024
STAMP & SIGNATURE:			DATE:		Signature Haliburton

Original - Client Files Copy - Area Office QC/FN/MPI/065 Rev.00 DATED 07 NOV 2021



Tel: +9647810009138 / +9647834964657
Email: OP@qualitycontrol-iraq.com
hany.akafi@qualitycontrol-iraq.com