





## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Hong Hua Oil & Gas Engineering Services, Ltd	<b>Job Number:</b>	QC-HH-06-24-0175																					
<b>Date of Examination:</b>	06.06.2024	<b>Location:</b>	HH-029																					
<b>Certificate No:</b>	QC-HH-06-24-0175-02-01																							
Serial Number:	QTY	Description	SWL	Date of last thorough examination																				
B4740 B4771 B4719 B4757 B4729	05	<p style="text-align: center;">SAFETY PIN BOW SHACKLE</p> <p>Size: 5/8" Grade: 6 Manufacture: TOYOLIFT Safety Factor: 6:1</p> <p style="text-align: center;">Location: Store</p> 	3 ¼ TON	NEW																				
<b>Reference Standard:</b>		BS EN 13889																						
Is this the first examination after Installation or assembly at a new site or location?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>	YES		NO	√	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?																	
YES		NO	√																					
If the answer to the above question is YES has the equipment been installed correctly?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> </table>	YES		NO		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>		YES	√	NO		YES		NO	√	YES	√	NO		YES		NO	√
YES		NO																						
YES	√	NO																						
YES		NO	√																					
YES	√	NO																						
YES		NO	√																					
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>																								
Is the above a defect which is of immediate danger to persons:				<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>	YES		NO	√																
YES		NO	√																					
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:																				
Particulars of any repair, renewal or alteration required to remedy the defect identified above:																								
Particulars of any tests carried out as part of the examination: (If none state NONE)																								
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory																								
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>				<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> </table>	YES	√	NO																	
YES	√	NO																						

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khalid Mahmoud	Mohamed Abdulla		05.12.2024

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operation Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Hong Hua Oil & Gas Engineering Services, Ltd		<b>Job Number:</b>	QC-HH-06-24-0175	
<b>Date of Examination:</b>	06.06.2024	<b>Location:</b>	HH-029	<b>Certificate No:</b>	QC-HH-06-24-0175-02-02
<b>Serial Number:</b>	<b>QTY</b>	<b>Description</b>		<b>SWL</b>	<b>Date of last thorough examination</b>
B2782 B4760 B4752 B4756 B2798	05	SAFETY PIN BOW SHACKLE  Size: 5/8" Grade: 6 Manufacture: TOYOLIFT Safety Factor: 6:1  Location: Store		3 ¼ TON	NEW
<b>Reference Standard:</b>		BS EN 13889			
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	√	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO		YES √ NO YES √ NO YES NO √
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES	NO √
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>				YES	NO √

REV: 01 Dated: 20 June 2022

<b>ASNT Level II Inspector Name:</b>	<b>Authenticating This Report:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Thorough Examination:</b>
Khalid Mahmoud	Mohamed Abdulla		05.12.2024

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operation Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Hong Hua Oil & Gas Engineering Services, Ltd	<b>Job Number:</b>	QC-HH-06-24-0175																				
<b>Date of Examination:</b>	06.06.2024	<b>Location:</b>	HH-029																				
<b>Certificate No:</b>	QC-HH-06-24-0175-02-03																						
Serial Number:	QTY	Description	SWL	Date of last thorough examination																			
B4759 B4743 B4750 B4758 B4741	05	SAFETY PIN BOW SHACKLE  Size: 5/8" Grade: 6 Manufacture: TOYOLIFT Safety Factor: 6:1  Location: Store	3 ¼ TON	NEW																			
<b>Reference Standard:</b>		BS EN 13889																					
Is this the first examination after Installation or assembly at a new site or location?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>	YES	NO	√	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?																	
YES	NO	√																					
If the answer to the above question is YES has the equipment been installed correctly?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> </table>	YES	NO		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>		YES	√	NO		YES		NO	√	YES	√	NO		YES		NO	√
YES	NO																						
YES	√	NO																					
YES		NO	√																				
YES	√	NO																					
YES		NO	√																				
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>																							
Is the above a defect which is of immediate danger to persons:			YES	NO																			
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:																				
Particulars of any repair, renewal or alteration required to remedy the defect identified above:																							
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory																							
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>			YES	NO																			

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khalid Mahmoud	Mohamed Abdulla		05.12.2024


**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Hong Hua Oil & Gas Engineering Services, Ltd	<b>Job Number:</b>	QC-HH-06-24-0175	
<b>Date of Examination:</b>	06.06.2024	<b>Location:</b>	HH-029	
<b>Certificate No:</b>	QC-HH-06-24-0175-02-04			
Serial Number:	QTY	Description	SWL	Date of last thorough examination
B4712 B4751 B4749 B4766 B4742	05	<p style="text-align: center;">SAFETY PIN BOW SHACKLE</p> <p>Size: 5/8" Grade: 6 Manufacture: TOYOLIFT Safety Factor: 6:1</p> <div style="text-align: center;">  </div> <p style="text-align: center;">Location: Store</p>	3 ¼ TON	NEW
<b>Reference Standard:</b>	BS EN 13889			
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		
		Was the examination carried out:		
		Within an interval of 6 months?	YES	✓ NO
		With an interval of 12 months?	YES	NO ✓
		In accordance with an examination scheme?	YES	✓ NO
		After the occurrence of exceptional circumstances?	YES	NO ✓
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>				
Is the above a defect which is of immediate danger to persons:			YES	NO ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:				
Particulars of any tests carried out as part of the examination: (If none state NONE)				
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory				
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>			YES	✓ NO

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khalid Mahmoud	Mohamed Abdulla		05.12.2024

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Hong Hua Oil & Gas Engineering Services, Ltd	<b>Job Number:</b>	QC-HH-06-24-0175																
<b>Date of Examination:</b>	06.06.2024	<b>Location:</b>	HH-029																
<b>Certificate No:</b>	QC-HH-06-24-0175-02-05																		
Serial Number:	QTY	Description	SWL	Date of last thorough examination															
B4939	01	SAFETY PIN BOW SHACKLE  Size: 7/8" Grade: 6 Manufacture: TOYOLIFT Safety Factor: 6:1  Location: Store	6 ½ TON	05.12.2023															
<b>Reference Standard:</b>		BS EN 13889																	
Is this the first examination after Installation or assembly at a new site or location?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>	YES		NO	√	Was the examination carried out: Within an interval of 6 months?												
YES		NO	√																
If the answer to the above question is YES has the equipment been installed correctly?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> </table>	YES		NO		With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?												
YES		NO																	
			<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>	YES	√	NO		YES		NO	√	YES	√	NO		YES		NO	√
YES	√	NO																	
YES		NO	√																
YES	√	NO																	
YES		NO	√																
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>																			
Is the above a defect which is of immediate danger to persons:			YES	√															
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:																
Particulars of any repair, renewal or alteration required to remedy the defect identified above:																			
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory																			
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>			YES	√															

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Thorough Examination:
Khalid Mahmoud	Mohamed Abdulla		05.12.2024

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Hong Hua Oil & Gas Engineering Services, Ltd	<b>Job Number:</b>	QC-HH-06-24-0175																					
<b>Date of Examination:</b>	06.06.2024	<b>Location:</b>	HH-029																					
<b>Certificate No:</b>	QC-HH-06-24-0175-02-06																							
Serial Number:	QTY	Description	SWL	Date of last thorough examination																				
J222	01	SAFETY PIN BOW SHACKLE  Size: 7/8" Grade: 6 Manufacture: MCKAT Safety Factor: 6:1  Location: Store	6 ½ TON	05.12.2023																				
<b>Reference Standard:</b>		BS EN 13889																						
Is this the first examination after Installation or assembly at a new site or location?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>	YES		NO	√	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?																	
YES		NO	√																					
If the answer to the above question is YES has the equipment been installed correctly?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> </table>	YES		NO		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>		YES	√	NO		YES		NO	√	YES	√	NO		YES		NO	√
YES		NO																						
YES	√	NO																						
YES		NO	√																					
YES	√	NO																						
YES		NO	√																					
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>																								
Is the above a defect which is of immediate danger to persons:				<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>	YES		NO	√																
YES		NO	√																					
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:																					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:																								
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory																								
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>				<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> </table>	YES	√	NO																	
YES	√	NO																						

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Thorough Examination:
Khalid Mahmoud	Mohamed Abdulla		05.12.2024


**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Hong Hua Oil & Gas Engineering Services, Ltd	<b>Job Number:</b>	QC-HH-06-24-0175
<b>Date of Examination:</b>	06.06.2024	<b>Location:</b>	HH-029
<b>Certificate No:</b>	QC-HH-06-24-0175-02-07		
<b>Serial Number:</b>	<b>QTY</b>	<b>Description</b>	<b>SWL</b>
J01	01	<p style="text-align: center;">SAFETY PIN BOW SHACKLE</p> <p>Size: 7/8" Grade: 6 Manufacture: DY Safety Factor: 6:1</p>  <p style="text-align: center;">Location: Store</p>	6 ½ TON
<b>Reference Standard:</b>	BS EN 13889		
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓
	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓
	YES	NO	✓
Was the examination carried out:		Within an interval of 6 months?	
		With an interval of 12 months?	
In accordance with an examination scheme?		After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>			
Is the above a defect which is of immediate danger to persons:			YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by: <input type="text"/>
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none state NONE)			
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory			
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>			YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>

REV: 01 Dated: 20 June 2022

<b>ASNT Level II Inspector Name:</b>	<b>Authenticating This Report:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
Khalid Mahmoud	Mohamed Abdulla		05.12.2024


**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Hong Hua Oil & Gas Engineering Services, Ltd	<b>Job Number:</b>	QC-HH-06-24-0175	
<b>Date of Examination:</b>	06.06.2024	<b>Location:</b>	HH-029	
<b>Certificate No:</b>	QC-HH-06-24-0175-02-08			
Serial Number:	QTY	Description	SWL	Date of last thorough examination
L4A	01	SAFETY PIN BOW SHACKLE  Size: 7/8" Grade: 6 Manufacture: GT Safety Factor: 6:1    Location: Store	6 ½ TON	05.12.2023
<b>Reference Standard:</b>	BS EN 13889			
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	Was the examination carried out: Within an interval of 6 months? <input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/> ✓ With an interval of 12 months? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> ✓	In accordance with an examination scheme? <input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/> ✓ After the occurrence of exceptional circumstances? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>				
Is the above a defect which is of immediate danger to persons:			<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:				
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory				
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>			<input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/> ✓	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khalid Mahmoud	Mohamed Abdulla		05.12.2024


**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






## CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Hong Hua Oil & Gas Engineering Services, Ltd	<b>Job Number:</b>	QC-HH-06-24-0175
<b>Date of Examination:</b>	06.06.2024	<b>Location:</b>	HH-029
<b>Certificate No:</b>	QC-HH-06-24-0175-02-09		
<b>Serial Number:</b>	<b>QTY</b>	<b>Description</b>	<b>SWL</b>
J98 15896	02	SAFETY PIN BOW SHACKLE  Size: 1 3/4" Grade: 6 Manufacture: GT Safety Factor: 6:1  Location: Store	25 TON
			05.12.2023
<b>Reference Standard:</b>	BS EN 13889		
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓
	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓
	YES	NO	✓
Was the examination carried out:		Within an interval of 6 months?	
		YES ✓ NO	
		With an interval of 12 months?	
		YES ✓ NO ✓	
In accordance with an examination scheme?		YES ✓ NO	
After the occurrence of exceptional circumstances?		YES NO ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) <b>NONE</b>			
Is the above a defect which is of immediate danger to persons:			YES NO ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none state NONE)			
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory			
<b>IS THIS EQUIPMENT SAFE TO OPERATE?</b>			YES ✓ NO

REV: 01 Dated: 20 June 2022

<b>ASNT Level II Inspector Name:</b>	<b>Authenticating This Report:</b>	<b>Signature &amp; Stamp:</b>	<b>Date of Next Through Examination:</b>
Khalid Mahmoud	Mohamed Abdulla		05.12.2024

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

