



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/01		
Serial Number	Description of the examined equipment		Result
B001	Lifting Lugs for Bunker		Pass
Lifting Lugs SN:	256 TO 259		




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/02		
Serial Number	Description of the examined equipment		Result
B002	Lifting Lugs for Bunker		Pass
Lifting Lugs SN:	283 TO 286		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/03
Serial Number	Description of the examined equipment			Result
B003	Lifting Lugs for Bunker			Pass
Lifting Lugs SN:	201 TO 204			




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/04		
Serial Number	Description of the examined equipment		Result
FWT01	Lifting Lugs for Fire Pump Store		Pass
Lifting Lugs SN:	37-221 TO 37-224		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/05		
Serial Number	Description of the examined equipment		Result
WT01	Lifting Lugs for Water Tank		Pass
Lifting Lugs SN:	37-312 TO 37-315		




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/06		
Serial Number	Description of the examined equipment		Result
1-1	Lifting Lugs for HSE Caravan		Pass
Lifting Lugs SN:	H-1 TO H-4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:			QC-DQ-03-24-0090-03/07
Serial Number	Description of the examined equipment		Result
OCLU 1307757	Lifting Point ISO Corner		Pass
Lifting Lugs SN:	/		




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/08		
Serial Number	Description of the examined equipment		Result
TEXU 5237709	Lifting Point ISO Corner		Pass
Lifting Lugs SN:	/		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:			QC-DQ-03-24-0090-03/09
Serial Number	Description of the examined equipment		Result
PPDU 070477	Lifting Point ISO Corner		Pass
Lifting Lugs SN:	/		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/10		
Serial Number	Description of the examined equipment		Result
111	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-325 TO 37-328		




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/11		
Serial Number	Description of the examined equipment		Result
100424	Lifting Lugs for Laundry 100424		Pass
Lifting Lugs SN:	37-329 TO 37-332		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/12		
Serial Number	Description of the examined equipment		Result
109	Lifting Lugs for W.C Camp		Pass
Lifting Lugs SN:	109-1 TO 109-4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/13		
Serial Number	Description of the examined equipment		Result
TTNU 1846310	Lifting Lugs for W.C		Pass
Lifting Lugs SN:	W1 TO W4		




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/14		
Serial Number	Description of the examined equipment		Result
206	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	206-1 TO 206-4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/15
Serial Number	Description of the examined equipment			Result
20-1	Lifting Lugs for Caravan			Pass
Lifting Lugs SN:	01 TO 04			




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:			QC-DQ-03-24-0090-03/16
Serial Number	Description of the examined equipment		Result
A-10216	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	16-1 TO 16-4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/17
Serial Number	Description of the examined equipment			Result
100416	Lifting Lugs for Caravan			Pass
Lifting Lugs SN:	37-201 TO 37-204			




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/18
Serial Number	Description of the examined equipment			Result
10231	Lifting Lugs for Caravan			Pass
Lifting Lugs SN:	A15 TO A18			




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/19
Serial Number	Description of the examined equipment			Result
37-1	Lifting Lugs for Skid of Camp			Pass
Lifting Lugs SN:	S10-1 TO S1-4			



NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure


Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/20
Serial Number	Description of the examined equipment			Result
37-2	Lifting Lugs for Skid of Camp			Pass
Lifting Lugs SN:	S2-1 TO S2-4			



NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure


Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/21		
Serial Number	Description of the examined equipment		Result
37-3	Lifting Lugs for Skid of Camp		Pass
Lifting Lugs SN:	S3-1 TO S3-4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/22		
Serial Number	Description of the examined equipment		Result
37-4	Lifting Lugs for Skid of Camp		Pass
Lifting Lugs SN:	S4-1 TO S4-4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/23
Serial Number	Description of the examined equipment			Result
37-5	Lifting Lugs for Skid of Camp			Pass
Lifting Lugs SN:	S5-1 TO S5-4			



NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure


Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/24
Serial Number	Description of the examined equipment			Result
37-6	Lifting Lugs for Skid of Camp			Pass
Lifting Lugs SN:	S6-1 TO S6-4			




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/25		
Serial Number	Description of the examined equipment		Result
37-7	Lifting Lugs for Skid of Camp		Pass
Lifting Lugs SN:	S7-1 TO S7-4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/26		
Serial Number	Description of the examined equipment		Result
37-8	Lifting Lugs for Skid of Camp		Pass
Lifting Lugs SN:	S8-1 TO S8-4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/27
Serial Number	Description of the examined equipment			Result
37-9	Lifting Lugs for Skid of Camp			Pass
Lifting Lugs SN:	S9-1 TO S9-4			



NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure


Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/28
Serial Number	Description of the examined equipment		Result
37-10	Lifting Lugs for Skid of Camp		Pass
Lifting Lugs SN:	S10-1 TO S10-4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:			QC-DQ-03-24-0090-03/29
Serial Number	Description of the examined equipment		Result
37-11	Lifting Lugs for Skid of Camp		Pass
Lifting Lugs SN:	S11-1 TO S11-4		




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/30
Serial Number	Description of the examined equipment		Result
11-3	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-205 TO 37-208		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/31
Serial Number	Description of the examined equipment		Result
11-2	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-209 TO 37-212		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/32
Serial Number	Description of the examined equipment		Result
13852	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-305 TO 37-308		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/33
Serial Number	Description of the examined equipment		Result
4-2	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-221 TO 37-224		




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/34
Serial Number	Description of the examined equipment		Result
100407	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-297 TO 37-300		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/35
Serial Number	Description of the examined equipment		Result
A-27262	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	A1 TO A4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/36
Serial Number	Description of the examined equipment		Result
100419	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-185 TO 37-188		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-10	Due Date	17-02-2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06-2025
Black Ink	7HF	Batch No:	220605	Due Date	7-1-2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/37
Serial Number	Description of the examined equipment		Result
4-1	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-193 TO 37-196		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/38
Serial Number	Description of the examined equipment		Result
100422	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-153 TO 37-156		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/39		
Serial Number	Description of the examined equipment		Result
7-2	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-001 TO 37-004		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/40
Serial Number	Description of the examined equipment		Result
100413	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-161 TO 37-164		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/41
Serial Number	Description of the examined equipment			Result
106	Lifting Lugs for Caravan			Pass
Lifting Lugs SN:	37-177 TO 37-180			



NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure


Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/42
Serial Number	Description of the examined equipment		Result
100418	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-173 TO 37-176		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/43
Serial Number	Description of the examined equipment		Result
3-1	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-169 TO 37-172		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/44
Serial Number	Description of the examined equipment		Result
100421	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-189 TO 37-192		




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.





Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/45
Serial Number	Description of the examined equipment			Result
5559	Lifting Lugs for Caravan			Pass
Lifting Lugs SN:	37-005 TO 37-008			



NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure


Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/46		
Serial Number	Description of the examined equipment		Result
6-3	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-181 TO 37-184		




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/47
Serial Number	Description of the examined equipment		Result
100427	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-217 TO 37-220		




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/48
Serial Number	Description of the examined equipment		Result
13849	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-301 TO 37-304		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
Certificate No:	QC-DQ-03-24-0090-03/49		
Serial Number	Description of the examined equipment		Result
1-2	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-225 TO 37-228		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company		Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037	Certificate No: QC-DQ-03-24-0090-03/50
Serial Number	Description of the examined equipment			Result
3-2	Lifting Lugs for Caravan			Pass
Lifting Lugs SN:	37-209 TO 37-212			



NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure


Visual and MPI carried out for the above description and found free of surface defects at the time of inspection

Identification of any part found to have a defect and a description of the defect:

None

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

None


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/51
Serial Number	Description of the examined equipment		Result
13928	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-265 TO 37-268		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/52
Serial Number	Description of the examined equipment		Result
13931	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-261 TO 37-264		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/53
Serial Number	Description of the examined equipment		Result
13847	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-281 TO 37-284		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/54
Serial Number	Description of the examined equipment		Result
13926	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-277 TO 37-280		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/55
Serial Number	Description of the examined equipment		Result
13924	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-273 TO 37-276		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/56
Serial Number	Description of the examined equipment		Result
2-2	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-293 TO 37-296		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/57
Serial Number	Description of the examined equipment		Result
100411	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-293 TO 37-296		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/58
Serial Number	Description of the examined equipment		Result
2-3	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-285 TO 37-288		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/59
Serial Number	Description of the examined equipment		Result
A-13845	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-137 TO 37-140		




NDT Equipment Details

Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025

NDT procedure

Visual and MPI carried out for the above description and found free of surface defects at the time of inspection
Identification of any part found to have a defect and a description of the defect:
None
Particulars of any repair, renewal or alteration required to remedy the defect identified above:
None


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations, Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/60
Serial Number	Description of the examined equipment		Result
100409	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-141 TO 37-144		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/61
Serial Number	Description of the examined equipment		Result
100408	Lifting Lugs for Caravan		Pass
Lifting Lugs SN:	37-145 TO 37-148		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/62
Serial Number	Description of the examined equipment		Result
CP01	Lifting Point for Control Pannal		Pass
Lifting Point SN:	CP-1 TO CP-4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					


ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




Visual & Magnetic Particles Examination Report

Client Name:	Daqing Drilling Company	Job Number:	QC-DQ-03-24-0090
Date of Examination:	13.03.2024	Location:	DQ Rig 037
		Certificate No:	QC-DQ-03-24-0090-03/63
Serial Number	Description of the examined equipment		Result
CP02	Lifting Point for Control Pannal		Pass
Lifting Point SN:	CP-5 TO CP-8		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	14.08.2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06.2025
Black Ink	7HF	Batch No:	220605	Due Date	07.01.2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		12.09.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.