



CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch	Job Number:	QC-ZPEC-05-24-0161
Date of Examination:	18.05.2024	Location:	ZPEC Rig 25
Certificate No:	QC-ZPEC-05-24-0161-05/01		


Serial Number:	QTY	Description	SWL	Date of last thorough examination
D18.06232048	01	Fall Arrestor Manufacture: Delta Plus Model: AN124T Length: 15 M Date of Manufacture: 08.2018	150 KG	16.11.2023

Reference Standard:	BS EN 360:2002
----------------------------	----------------

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	✓	NO	✓
				With an interval of 12 months?	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme?	YES	✓	NO	
				After the occurrence of exceptional circumstances?	YES		NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE			
Is the above a defect which is of immediate danger to persons:	YES	NO	✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)	YES by:		
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory			
IS THIS EQUIPMENT SAFE TO OPERATE?			
	YES	✓	NO

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdullah		17.11.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch			Job Number:	QC-ZPEC-05-24-0161												
Date of Examination:	18.05.2024	Location:	ZPEC Rig 25	Certificate No:	QC-ZPEC-05-24-0161-05/02												
Serial Number:	QTY	Description		SWL	Date of last thorough examination												
00721700645	01	Fall Arrestor Manufacture: Miller Model: 1034131-1 Length: 15 M Date of Manufacture: 22.02.2017		150 KG	16.11.2023												
Reference Standard:		BS EN 360:2002															
Is this the first examination after Installation or assembly at a new site or location? If the answer to the above question is YES has the equipment been installed correctly?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td></td> </tr> </table>		YES		NO	✓	YES		NO		Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?					
				YES		NO	✓										
YES		NO															
<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td>YES</td> <td>✓</td> <td>NO</td> <td></td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> <tr> <td>YES</td> <td>✓</td> <td>NO</td> <td></td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td>✓</td> </tr> </table>		YES	✓	NO		YES		NO	✓	YES	✓	NO		YES		NO	✓
YES	✓	NO															
YES		NO	✓														
YES	✓	NO															
YES		NO	✓														
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE																	
Is the above a defect which is of immediate danger to persons:				YES													
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:													
Particulars of any repair, renewal or alteration required to remedy the defect identified above:																	
Particulars of any tests carried out as part of the examination: (If none state NONE)																	
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory																	
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	✓												

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Thorough Examination:
Khaled Mahmoud	Mohamed Abdullah		17.11.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch	Job Number:	QC-ZPEC-05-24-0161
Date of Examination:	18.05.2024	Location:	ZPEC Rig 25
Certificate No:	QC-ZPEC-05-24-0161-05/03		

Serial Number:	QTY	Description	SWL	Date of last thorough examination
2308023	01	Fall Arrestor Manufacture: Rigman Model: MRFA100SRL Length: 10 M Date of Manufacture: 08.2023	140 KG	16.11.2023

Reference Standard:	BS EN 360:2002
----------------------------	----------------

Is this the first examination after Installation or assembly at a new site or location?	YES		NO				Was the examination carried out: Within an interval of 6 months?	YES		NO	
							With an interval of 12 months?	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES		NO				In accordance with an examination scheme?	YES	✓	NO	
							After the occurrence of exceptional circumstances?	YES		NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons:	YES		NO	
--	-----	--	----	--


Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) YES by:

Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE?	YES	✓	NO	
---	-----	---	----	--

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdullah		17.11.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch			Job Number:	QC-ZPEC-05-24-0161
Date of Examination:	18.05.2024	Location:	ZPEC Rig 25	Certificate No:	QC-ZPEC-05-24-0161-05/04

Serial Number:	QTY	Description	SWL	Date of last thorough examination
M 3117 M 3118 M 3120	03	Flat Polyester Woven Webbing Sling Manufacture: Safety Marin Date of Manufacture: 03.2024 Type: Webbing Sling Material: Polyester Safety Factor: 7:1 Length: 10 M Color: Red  Location: Store	Vertical 5000 Kg Choker 4000 Kg Basket 10000 Kg	03.2024

Reference Standard:	BS EN 1492-1:2008		
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓
Was the examination carried out:			
Within an interval of 6 months?		YES	✓ NO
With an interval of 12 months?		YES	✓ NO
In accordance with an examination scheme?		YES	✓ NO
After the occurrence of exceptional circumstances?		YES	✓ NO
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE			
Is the above a defect which is of immediate danger to persons:			YES NO ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none state NONE)			
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory			
IS THIS EQUIPMENT SAFE TO OPERATE?			YES ✓ NO

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdullah		17.11.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch	Job Number:	QC-ZPEC-05-24-0161
Date of Examination:	18.05.2024	Location:	ZPEC Rig 25
Certificate No:	QC-ZPEC-05-24-0161-05/05		

Serial Number:	QTY	Description	SWL	Date of last thorough examination
Z 1569 Z 6256	02	Flat Polyester Woven Webbing Sling Manufacture: Safety Marin Date of Manufacture: 03.2022 Type: Webbing Sling Material: Polyester Safety Factor: 7:1 Length: 10 M Color: Red  Location: Store	Vertical 10000 Kg Choker 8000 Kg Basket 20000 Kg	16.11.2023

Reference Standard:	BS EN 1492-1:2008		
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓
Was the examination carried out:			
Within an interval of 6 months?		YES	✓ NO
With an interval of 12 months?		YES	✓ NO
In accordance with an examination scheme?		YES	✓ NO
After the occurrence of exceptional circumstances?		YES	✓ NO
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE			
Is the above a defect which is of immediate danger to persons:			YES NO ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none state NONE)			
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory			
IS THIS EQUIPMENT SAFE TO OPERATE?			YES ✓ NO

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdullah		17.11.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch	Job Number:	QC-ZPEC-05-24-0161
Date of Examination:	18.05.2024	Location:	ZPEC Rig 25
Certificate No:	QC-ZPEC-05-24-0161-05/06		


Serial Number:	QTY	Description	SWL	Date of last thorough examination
B6243 B6245 B6265	03	Flat Polyester Woven Webbing Sling Manufacture: Safety Marin Date of Manufacture: 10.2023 Type: Webbing Sling Material: Polyester Safety Factor: 7:1 Length: 6 M Color: Red  Location: Store	Vertical 5000 Kg Choker 4000 Kg Basket 10000 Kg	16.11.2023

Reference Standard:	BS EN 1492-1:2008		
----------------------------	-------------------	--	--

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	YES	✓	NO	✓
				With an interval of 12 months?	YES		NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme?	YES	✓	NO	
				After the occurrence of exceptional circumstances?	YES		NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE			
Is the above a defect which is of immediate danger to persons:			YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by: <input type="text"/>
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none state NONE)			
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory			
IS THIS EQUIPMENT SAFE TO OPERATE?			YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdullah		17.11.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch			Job Number:	QC-ZPEC-05-24-0161
Date of Examination:	18.05.2024	Location:	ZPEC Rig 25	Certificate No:	QC-ZPEC-05-24-0161-05/07

Serial Number:	QTY	Description	SWL	Date of last thorough examination
95282-36/15	01	Flat Polyester Woven Webbing Sling Manufacture: Liftek Date of Manufacture: 10.10.2022 Type: Webbing Sling Material: Polyester Safety Factor: 7:1 Length: 6 M Color: Red  Location: Store	Vertical 5000 Kg Choker 4000 Kg Basket 10000 Kg	16.11.2023

Reference Standard:	BS EN 1492-1:2008		
----------------------------	-------------------	--	--

Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out:	YES	✓	NO	✓
				Within an interval of 6 months?	YES		NO	✓
				With an interval of 12 months?	YES	✓	NO	
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme?	YES	✓	NO	✓
				After the occurrence of exceptional circumstances?	YES		NO	✓

Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) **NONE**

Is the above a defect which is of immediate danger to persons: YES ☐ NO ☒

Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when) YES by:


Particulars of any repair, renewal or alteration required to remedy the defect identified above:

Particulars of any tests carried out as part of the examination: (If none state NONE)

The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory

IS THIS EQUIPMENT SAFE TO OPERATE?	YES	✓	NO	
---	-----	---	----	--

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdullah		17.11.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch			Job Number:	QC-ZPEC-05-24-0161
Date of Examination:	18.05.2024	Location:	ZPEC Rig 25	Certificate No:	QC-ZPEC-05-24-0161-05/08

Serial Number:	QTY	Description	SWL	Date of last thorough examination
C4902 C4990 C4892	03	Flat Polyester Woven Webbing Sling Manufacture: Safety Marin Date of Manufacture: 02.2024 Type: Webbing Sling Material: Polyester Safety Factor: 7:1 Length: 10 M Color: Red  Location: Store	Vertical 10000 Kg Choker 8000 Kg Basket 20000 Kg	16.11.2023

Reference Standard:	BS EN 1492-1:2008		
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	
Was the examination carried out:			
Within an interval of 6 months?		YES	NO
With an interval of 12 months?		YES	NO
In accordance with an examination scheme?		YES	NO
After the occurrence of exceptional circumstances?		YES	NO
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE			
Is the above a defect which is of immediate danger to persons:			YES NO ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none state NONE)			
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory			
IS THIS EQUIPMENT SAFE TO OPERATE?			YES ✓ NO

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdullah		17.11.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch	Job Number:	QC-ZPEC-05-24-0161
Date of Examination:	18.05.2024	Location:	ZPEC Rig 25
Certificate No:	QC-ZPEC-05-24-0161-05/09		

Serial Number:	QTY	Description	SWL	Date of last thorough examination
8728 8742	02	Flat Polyester Woven Webbing Sling Manufacture: Safety Marin Date of Manufacture: 04.2018 Type: Webbing Sling Material: Polyester Safety Factor: 7:1 Length: 12 M Color: Orange  Location: Store	Vertical 12000 Kg Choker 9600 Kg Basket 24000 Kg	16.11.2023

Reference Standard:	BS EN 1492-1:2008		
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO	✓
Was the examination carried out:			
Within an interval of 6 months?		YES	NO
Within an interval of 12 months?		YES	NO
In accordance with an examination scheme?		YES	NO
After the occurrence of exceptional circumstances?		YES	NO
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE			
Is the above a defect which is of immediate danger to persons:		YES	NO
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)		YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:			
Particulars of any tests carried out as part of the examination: (If none state NONE)			
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory			
IS THIS EQUIPMENT SAFE TO OPERATE?		YES	NO

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdullah		17.11.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.