




CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hong Hua Oil & Gas Engineering Services, Ltd	Job Number:	QC-HH-06-24-0175	
Date of Examination:	06.06.2024	Location:	HH-029	
Certificate No:	QC-HH-06-24-0175-07-01			
Serial Number:	QTY	Description	SWL	Date of last thorough examination
18-750-DJ09	01	Basket Stretcher A rescue System Basket Stretcher Manufacture: SPENCER PROTECTA Model: WJD4-1 Net Weight: 20Kg Gross Weight: 320Kg Product Size (L x W x H) 222 x 62 x 18cm Location: Rig Floor	300 KG	NEW
Reference Standard:		LOLER, EN ISO 15223-1:2012 & EN ISO 14971:2012, (BS EN 365)		
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	Was the examination carried out:	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> ✓	Within an interval of 6 months? <input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/> ✓ Within an interval of 12 months? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓ In accordance with an examination scheme? <input type="checkbox"/> YES <input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/> ✓ After the occurrence of exceptional circumstances? <input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE				
Is the above a defect which is of immediate danger to persons:			<input type="checkbox"/> YES	<input type="checkbox"/> NO <input checked="" type="checkbox"/> ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:				
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory				
IS THIS EQUIPMENT SAFE TO OPERATE?			<input type="checkbox"/> YES	<input checked="" type="checkbox"/> ✓ <input type="checkbox"/> NO <input type="checkbox"/> ✓

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hong Hua Oil & Gas Engineering Services, Ltd	Job Number:	QC-HH-06-24-0175																					
Date of Examination:	06.06.2024	Location:	HH-029																					
		Certificate No:	QC-HH-06-24-0175-07-02																					
Serial Number:	QTY	Description	SWL	Date of last thorough examination																				
6573960	01	TRIPOD HAND WINCH Manufacture: KARAM Model: RT-025 Manufacture Year: 11/2021 With Rescue Lifting Device Class B S. No: 6410735 Wire Rope Length: 30 M Wire Rope Dia: 5 MM Location: Mud System	180 KG	05.12.2023																				
Reference Standard:		BS EN 795: 2021 & EN 1496-2006																						
Is this the first examination after Installation or assembly at a new site or location?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>	YES		NO	√	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?																	
YES		NO	√																					
If the answer to the above question is YES has the equipment been installed correctly?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> </table>	YES		NO		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>		YES	√	NO		YES		NO	√	YES	√	NO		YES		NO	√
YES		NO																						
YES	√	NO																						
YES		NO	√																					
YES	√	NO																						
YES		NO	√																					
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE																								
Is the above a defect which is of immediate danger to persons:			YES	NO																				
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:																					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:																								
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory																								
IS THIS EQUIPMENT SAFE TO OPERATE?			YES	NO																				

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operation Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hong Hua Oil & Gas Engineering Services, Ltd			Job Number:	QC-HH-06-24-0175		
Date of Examination:	06.06.2024	Location:	HH-029	Certificate No:	QC-HH-06-24-0175-07-03		
Serial Number:	QTY	Description		SWL	Date of last thorough examination		
AL1	01	<p>4-Leg Chain Sling</p> <p>Manufacture: Safety Marine Diameter: 8 MM Length: 1.5 M Grade: 8</p>  <p>Master link C/W Chain Connector At The Top & Clevis Self –Lock Hook At The End. Safety Factor: 4:1</p> <p>Location: Harness Box</p>		4.2 Ton	NEW		
Reference Standard:		BS EN 818-4: 1996 + A1 2008					
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		Was the examination carried out:		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				Within an interval of 6 months?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/>		With an interval of 12 months?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				In accordance with an examination scheme?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	
				After the occurrence of exceptional circumstances?		<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE							
Is the above a defect which is of immediate danger to persons:						<input type="checkbox"/> YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:			
Particulars of any repair, renewal or alteration required to remedy the defect identified above:							
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory							
IS THIS EQUIPMENT SAFE TO OPERATE?						<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Thorough Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operation: Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hong Hua Oil & Gas Engineering Services, Ltd	Job Number:	QC-HH-06-24-0175	
Date of Examination:	06.06.2024	Location:	HH-029	
Certificate No:	QC-HH-06-24-0175-07-04			
Serial Number:	QTY	Description	SWL	Date of last thorough examination
30390 , 30400	01	Tow Leg Chain Sling Bushing Lifter Manufacture: Safety Marine Two leg chine sling 10 mm chine dia x1.8 m length Gread 8 connected with single master link 5/8" wll3 ton on top and connected with two chain link (10-8) wll 3.15 ton and two bushing hook at bottom Location: Rig Floor	1 Ton	05.12.2023
Reference Standard:	BS EN 818-4: 1996 + A1 2008			
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		
		Was the examination carried out:		
		Within an interval of 6 months?	YES	✓ NO
		With an interval of 12 months?	YES	NO ✓
		In accordance with an examination scheme?	YES	✓ NO
		After the occurrence of exceptional circumstances?	YES	NO ✓
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE				
Is the above a defect which is of immediate danger to persons:			YES	NO ✓
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:				
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory				
IS THIS EQUIPMENT SAFE TO OPERATE?			YES	✓ NO

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operation Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hong Hua Oil & Gas Engineering Services, Ltd	Job Number:	QC-HH-06-24-0175																					
Date of Examination:	06.06.2024	Location:	HH-029																					
Certificate No:	QC-HH-06-24-0175-07-05																							
Serial Number:	QTY	Description	SWL	Date of last thorough examination																				
M3515	01	<p style="text-align: center;">EYE LATCH HOOK</p> <p>Manufacture: BASH-P Eye Hook Dia: 39 Hook Size: 7/8-8"</p> <p style="text-align: center;">  </p> <p>Safety Factor: 4:1 Location: Harness Box</p>	5.3 Ton	NEW																				
Reference Standard:		BS EN 1677																						
Is this the first examination after Installation or assembly at a new site or location?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>	YES		NO	√	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td style="text-align: center;">√</td> </tr> <tr> <td>YES</td> <td style="text-align: center;">√</td> <td>NO</td> <td></td> </tr> <tr> <td>YES</td> <td></td> <td>NO</td> <td style="text-align: center;">√</td> </tr> </table>	YES	√	NO		YES		NO	√	YES	√	NO		YES		NO	√
YES		NO	√																					
YES	√	NO																						
YES		NO	√																					
YES	√	NO																						
YES		NO	√																					
If the answer to the above question is YES has the equipment been installed correctly?		<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> </table>	YES		NO																			
YES		NO																						
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE																								
Is the above a defect which is of immediate danger to persons:				<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%;"></td> <td style="width: 25%;">NO</td> <td style="width: 25%; text-align: center;">√</td> </tr> </table>	YES		NO	√																
YES		NO	√																					
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:																				
Particulars of any repair, renewal or alteration required to remedy the defect identified above:																								
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory																								
IS THIS EQUIPMENT SAFE TO OPERATE?				<table border="1" style="width: 100%; border-collapse: collapse;"> <tr> <td style="width: 25%;">YES</td> <td style="width: 25%; text-align: center;">√</td> <td style="width: 25%;">NO</td> <td style="width: 25%;"></td> </tr> </table>	YES	√	NO																	
YES	√	NO																						

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024


THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.






CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Hong Hua Oil & Gas Engineering Services, Ltd	Job Number:	QC-HH-06-24-0175							
Date of Examination:	06.06.2024	Location:	HH-029							
Certificate No:	QC-HH-06-24-0175-07-06									
Serial Number:	QTY	Description	Max. Load	Date of last thorough examination						
18617294	01	Rescue Descent Device Manufacture: Canasafe Manufacture Date: 02/2019 Part No: 55100 Descent Max. Height: 200 M  Location: Dog House	200 Kg	NEW						
Reference Standard:	BS EN 341:1992									
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	√	Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	√	NO			
					YES		NO	√		
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO			YES	√	NO			
					YES		NO	√		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE										
Is the above a defect which is of immediate danger to persons:							YES		NO	√
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						YES by:				
Particulars of any repair, renewal or alteration required to remedy the defect identified above:										
Particulars of any tests carried out as part of the examination: (If none state NONE) The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory										
IS THIS EQUIPMENT SAFE TO OPERATE?							YES	√	NO	

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Thorough Examination:
Khaled Mahmoud	Mohamed Abdulla		05.12.2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operation Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



