

CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch			Job Number:	QC-ZPEC-06-24-0191
Date of Examination:	24.June.2024	Location:	RIG ZPEC 25	Certificate No:	QC-ZPEC-06-24-0191/07
Serial Number:	QTY	Description		MBL	Date of last Thorough examination
B7115	01	SINGLE LEG WIRE ROPE SLINGE 19 mm Diameter, 120 M Length, Const.6×36, IWRC, RHO, Galv Steel IWRC, MECHANICALLY SPLICED WITH ALUMINUM FERRULE. Hard Eye X Plain. FOS: 5:1		23.10 MT	01-01-2024
Reference Standard:		BS EN 13414-1+A2:2008			
Is this the first examination after Installation or assembly at a new site or location?		YES ☒ NO ☐ YES ☒ NO ☐		Was the examination carried out: Within an interval of 6 months? With an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	
If the answer to the above question is YES has the equipment been installed correctly?		YES ☒ NO ☐ YES ☒ NO ☐		YES ☒ NO ☐ YES ☒ NO ☐	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES ☐	NO ☒
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES ☒	NO ☐
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp:		
Mohamed Abdalla	Ashraf El Said				
Date of Next Through Examination:	23.Dec.2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.