Al TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

CERTIFICATE OF QUALIFICATION VISUAL INSPECTION AND LEAK TESTING

THIS REPORT COMPLIES WITH RECOGNIZED INTERNATIONAL STANDARDS & TECHNICAL REQUIEREMENTS

CLIENT:	**HALLIBURTON (HPS)**		
LOCATION:	HPS PE YARD	**REPORT No.:**	QC-24-08-HPS-NDT-080-1
STANDARD:	CUSOMER SPECIFICATION	**JOB NO:**	20724
INSPECTION DATE:	Monday, August 12, 2024	**Due Date**	Tuesday, February 11, 2025
TYPE OF INSPECTION:	***VISUAL TESTING AND *LEAK TESTING**		
DESCRIPTION:	**FRAC TANK**	**SAP NO:**	**11873151**
MEDIUM USED:	**WATER**	**HOLDING TIME:**	**15 MINUTES**

PICTURES



INSPECTION RESULT

VISUAL TESTING:	Visual Testing of Frac Tank did not found Deforms Mechanical Damage, Cracks and Corrosion. At time of Inspection.
LEAK TESTING:	Leak Testing of Frac Tank did not found any leakage during the holding time. At time of Inspection.

Inspection Evaluation

VISUAL TESTING-The above mentioned Frac Tank was found "Satisfactory" Fit for intended used.

LEAK TESTING- The above mentioned Frac Tank was found "Satisfactory" Fit for intended used.

PERSONNEL DETAILS			**REVIEW BY**		
NAME:	RAO SOHAIL		**SENIOR INSPECTOR:**	NAVEED HUSSAIN	**CUSTOMER NAME**
QUALIFICATION:	ASNT LEVEL II MT,PT,VT		**SUPERVISOR:**	HANI ALI	
STAMP & SIGNATURE:			**DATE:**		

Original - Client Files Copy - Area Office QC/FN/MPI/065 Rev.00 DATED 07 NOV 2021

Tel: +9647810009138 / +9647834964657
Email: OP@qualitycontrol-iraq.com
hany.akafi@qualitycontrol-iraq.com