

AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	02-06-2024	Date of Report:	02-06-2024	Certificate No:	QQC-Halliburton-2024-0237-01
Client Name:	Halliburton	Location:	HCT	Job Number:	QC-Halliburton-2024-0237
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
10951695 10951632 10951684 10951661	04	WEBBING SLING MANUFACTURE: TOHO LENGTH: 4M COLOR: RED F.O.S: 7:1	5 T	11/2014	NEW
Reference Standard:	BS EN 1492-1 / HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1				
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☒ NO ☐ √		Was the examination carried out: Within an interval of 6 months? ☐ YES ☒ NO ☐ √ With an interval of 12 months? ☐ YES ☐ NO ☒ √ In accordance with an examination scheme? ☐ YES ☒ NO ☐ √ After the occurrence of exceptional circumstances? ☐ YES ☐ NO ☒ √	
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☒ NO ☐ √			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				☐ YES ☐ NO ☒ √	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				☐ YES ☒ √ ☐ NO ☐ √	
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp:		
AIZAZ FARHAT	ASHRAF ELSAID				
Date of Next Through Examination:	01-12-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	02-06-2024	Date of Report:	02-06-2024	Certificate No:	QQC-Halliburton-2024-0237-02
Client Name:	Halliburton	Location:	HCT	Job Number:	QC-Halliburton-2024-0237
Serial Number:	QTY	Description	SWL	Date of manufacture if known:	Date of last thorough examination
12261777 12261922	02	WEBBING SLING MANUFACTURE: TOHO LENGTH: 3M COLOR: YELLOW F.O.S: 7:1	3 T	11/2022	NEW
Reference Standard:		BS EN 1492-1 / HAL DOC: WM-GL-HAL-HSE-0420F & WM-GL-HAL-HSE-0420C REV 1			
Is this the first examination after Installation or assembly at a new site or location?		☐ YES ☒ NO ☐ √		Was the examination carried out:	
				Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?		☐ YES ☒ NO ☐ √		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES	NO
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	NO
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp:		
AIZAZ FARHAT	ASHRAF ELSAID				
Date of Next Through Examination:	01-12-2024				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

