



Visual & Magnetic Particles Examination Report

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd: Iraq		Job Number:	QC-HH-July-24-0203
Date of Examination:	14-July-2024	Location:	HH Rig 029	Certificate No: QC-HH-07-24-0200- BL005
Serial Number	Description of the examined equipment			Result
30390, 30400	Tow Leg Chain Sling (Bushing Lifter)			Pass
Dimension:	10mm x 1.8 m	SWL:	1TON	



NDT Equipment Details

Standard	ASTM E 709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-10	Due Date	12-Aug-2024
White Contrast	WCP-2	Batch No:	220602	Due Date	Jun-2025
Black Ink	7HF	Batch No:	220605	Due Date	Jan-2025

NDT Procedure:


***Visual and MPI Carried Out For The Above Description and Found Free of Surface Defects At The Time of Inspection:

Identification of Any Part Found To Have A Defect And A Description of The Defect:

None:

Particulars of Any Repair, Renewal or Alteration Required To Remedy The Defect Identified Above:


None:

Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Syed Aamir Ali	Mohamed Abdullah		13-Jan-2025

REV: 01 Dated: 20 June 2022





Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Syed Aamir Ali	Mohamed Abdullah		13-Jan-2025

REV: 01 Dated: 20 June 2022

