

AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



AFTER REPAIR INSPECTION CERTIFICATE OF 3 1/2" HWDP

Client Name:	Hilong Oil Services & Engineering	Report No.:	HL22-QC-24-07-NA.007
Acceptance Creater:	<input checked="" type="checkbox"/> API SPEC 7-2	Date of Inspection:	11.JULY.2024
Work Location:	ABERDEEN WORKSHOP	Rig No.:	HL-22
Test Equipment & Consumeable Details			
WHITE CONTRAST WCP-2	Batch #: 220602 Manufacture: Magnaflux Exp Date: JUN,2025	TECHNICAL DETAILS	Wet Visible Continuous
BLACK INK 7HF	Batch#.220605 Manufacture: Magnaflux Exp Date: JULY.2025	COIL(1200 AMP-TURNS/IN	22713 Cal.15.FEB.2024 Cal Due14.OCT.2024
FLUORESCENT 14HF	Batch #: 220306 Manufacture: Magnaflux Exp Date: March.2025	A.C HAND YOKE	PY-10 Cal.15.FEB.2024 Cal Due14.OCT.2024
INTENSITY METER	SR#1608000134 CAL.Date .15.FEB.2024 Cal Due14.OCT.2024	UV BLACK LIGHT	SR#1946875 Cal.15.FEB.2024 Cal Due14.OCT.2024
LEAD GAGE	SR#AH07KF0027 GAEMAKER LG-5003 Cal.15.FEB.2024 Cal Due14.OCT.2024	THREAD PROFILE GAGE	SR#21336 Cal.15.FEB.2024 Cal Due14.OCT.2024 SR#21335 Cal.15.FEB.2024 Cal Due14.OCT.2024
Magnetic Partical Concentration 7 HF	1.2 TO 2.4 ML/100 ML	WMPT Light Intensity	3500 Lux
Magnetic particle concentration flourcent 14 HF	0.1 TO 0.4 ML/100 ML	UV LIGHT INTENSITY:	3050 μw/cm ²
Magnetism Direction (Longitudinal)			
METHODOLOGY:	• Through Visual inspection •MPI inspection with Ultraviolet light • Dimensional Inspection *Lead Gaiging, & Thread Profile Gaiging.		
Connection:	3 1/2" IF	Size:	3 1/2"

Serial No.	Visual Inspection			Black Light		Dimensional 3 Inspection															
	Pin	Box	Body	Pin	Box	Pin						Box						Body			
						OD (in)	ID (in)	SRG (in)	SRG (in)	Bevel (in)	pin (in)	OD (in)	CB (in)	CB (in)	BB (in)	BB (in)	Bevel (in)	Pin Tong (in)	Box Tong (in)	C.W Pad OD (in)	length (in)
132A0061	--	Acc	-	--	Acc	--	--	--	--	--	--	5"	4 2/32"	5/8"	3 15/32"	7 7/8"	4 9/16"	--	16 3/4"	--	--
132A0191	--	Acc	-	--	Acc	--	--	--	--	--	--	5"	4 2/32"	5/8"	3 15/32"	7 7/8"	4 9/16"	--	17 1/8"	--	--

Conclusion : 02 Joint The Above Mentioned 3 1/2" Heavy Weight Drill Pipe was Found Acceptable from Box Connection After Repair at the time of Inspection, Ready to use.

Abbreviations :

OD Outside Diameter	ID Inside Diameter	SRG Stress Relief Groove	CB Counter Bore	BB Bore Back	FB Float Bore	
EGR Elevator Groove Recess	SGR Slip Groove Recess	CR Crack	B Bent	PC Premium Class	RF Reface	
GT Galled Thread	TP Thread Pitting	SP Seal Pitting	TD Thread Damage	SD Seal Damage	M Mashed	
1 100 % Coating	2 99-71 % Coating	3 70-40 % Coating	4 Up to 40 %	5 Nil	WT Wall Thickness	
Colors Code:		White No Defects	Red Crack or Extreme Damage.	Blue Damage	Green Seal Damage	Yellow ACFM

Inspector Name:	Review By				
Qualification:	Senior Inspector:	M. SARWAR	Supervisor:	RAO SOHAIL	Customer Name:
Signature:					Customer Signature:
Original – Client File Copy - Area Office QC/FN/DPI/NDT/006 Rev.00 DATED 07.NOV.2021					

