




LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Al- karrar Engineering Company			Certificate No:	QC-J-7-2024-0117/01
Date of Examination:	06.07.2024	Location:	Al- karrar Yard	Job Number:	QC-J-7-2024-0117
Equipment Serial No:	4390			SWL:	11500 KG
Description of Equipment	Truck Mounted Hydraulic Operated Telescopic Boom Lorry Crane (HIAB) Manufacture: FASSI Manufacture Year: 2012 Model: F300B/360B XP 24 MAX Radius: 12.20 M MAX Boom Length: 12.20 M Chasses NO: YS2R6X200B2065934 Safety Latch Hook WLL: 15 TON & SN: L692 Shackle SWL 17 TON & SN: L693 Registration No: 22-B 23867				
Ref. Standard	BS 7121-2-4				
PERFORMANCE TEST	BOOM LENGTH	RADIUS	SWL	APPLIED LOAD (KG)	
	2.55 M	2.55 M	11500 KG	FUNCTION TEST	
	8.10 M	8.10 M	3795 KG	3812 KG	
Date of Last Examination:	25.04.2022		Date of Last Proof Load Test:	25.04.2022	
Examination Type	Pass	Fail	Notes		
Operational (No Load)	√		Elevating Work Platform Found Satisfactory For Further Use.		
Performance Test (Rated Capacity)	√		Elevating Work Platform found to be acceptable to lift 100 % from SWL .		
Proof Load Test (1.25 x Rated Capacity)	--		Proof Load Test Shall Be Done After any Repair/ Modification		
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	Was the examination carried out: Within an interval of 6 months? Within an interval of 12 months? In accordance with an examination scheme? After the occurrence of exceptional circumstances?	YES	NO
		√		YES	NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		YES	NO
				YES	NO
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES	NO
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) In the light of inspection findings subject {HIAB} was Inspected visually, operationally and performance test And Proof Load Test was performed where no defects were observed during testing Hence, it was found satisfactory and fit for intended use					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	NO

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.07.2025

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Al- karrar Engineering Company		Location:	Al- karrar Yard
Description of Equipment:	Truck Mounted Hydraulic Operated Telescopic Boom Lorry Crane (HIAB)		Serial No:	4390
Date of Examination:	06.07.2024	Certificate No:	QC-J-7-2024-0117/01	SWL: 11500 KG

HIAB Inspection Checklist


No	COMPONANT CHECKS	RESULT	COMMENTS
DATA PLATE			
1	WHEELS & TYRES	√	
2	ANGLE INDICATOR	√	
3	EMERGENCY KEY	√	
4	OPERATING EVERS & PEDALES	√	
5	LIGHT INDICATORE & HORN	√	
6	INTEGRITY OF CHASSSIS	√	
7	OUTRIGGERS & HOSUSING	√	
8	LEVEL INDICATORS	√	
9	LIGHTS & HORN	√	
10	HYDRULIC SYSTEM	√	
11	PRIM MOTIVE POWER UNIT	√	
12	OPERATORE MANUAL & LOAD CHART	√	
13	PLATE FORM DECK & ACCESS	√	
14	AXLES	√	
15	BREAKS & CLUTCHES	√	
16	STEERING	√	
17	CABIN CONDITION & ACCESS	√	
18	MAIN HOIST DRUM	N/A	
19	MINIMUM TURNS OF DRUM	N/A	
20	ROPES & ANCHORAGES	N/A	
21	BASKET CONDATION	√	
22	BOOM LIFT	√	
23	WEAR BADS	√	
24	HYDRULLIC HOSES	√	
25	BOOM SECTION FOR DAMAGE	√	
26	SLEW MOTOR & GEAR	√	
27	OIL LEAKAGES OF OPERATION	√	
28	GENERAL CONDITIONS	√	
29	EMERGENCY LOWERING SYSTEM	√	

NOTE:

* HIAB visual, function & performance test were carried out and found accept at the time of inspection.

Key Category:

1 = Immediate action	2= Action within ...	3= Worn/Serviceable	✓ No Apparent Defects	N/A = Not Applicable
----------------------	----------------------	---------------------	-----------------------	----------------------

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.07.2025

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned own work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Al- karrar Engineering Company		Location:	Al- karrar Yard	
Description of Equipment:	Truck Mounted Hydraulic Operated Telescopic Boom Lorry Crane (HIAB)		Serial No:	4390	
Date of Examination:	06.07.2024	Certificate No:	QC-J-7-2024-0117/01	SWL:	11500 KG

PICTORIAL



ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.07.2025

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.




LIFTING EQUIPMENT CERTIFICATE OF VISUAL & THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Al- karrar Engineering Company		Location:	Al- karrar Yard
Description of Equipment:	Truck Mounted Hydraulic Operated Telescopic Boom Lorry Crane (HIAB)		Serial No:	4390
Date of Examination:	06.07.2024	Certificate No:	QC-J-7-2024-0117/01	SWL: 11500 KG



ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Khaled Mahmoud	Mohamed Abdulla		05.07.2025

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations and Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.