




CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch	Certificate No:	QC-ZPEC-06-24-0190-02	
Date of Examination:	28-Jun-2024	Location:	ZPEC Rig - 25 RU - 620	
Job Number:	QC-ZPEC-06-24-0190			
Serial Number:	QTY	Description:	MBL:	Date of Last Thorough Examination:
CN D003350200	01	SINGLE LEG WIRE ROPE SLING 6X36 IWRC, ROPE GRAED 1960 N/MM2 GALV MECHANICALLY SPLICED WITH ALUMINUM FERRULE STEEL CORE: Hard Eye At Both Ends: Dim: 22 mm Dia X 89.0 M (L) FOS: 5:1 Location: Cat Walk Drum	339 KN	Oct-2023
Reference Standard:	BS EN 13414-1			
Is this the first examination after Installation or assembly at a new site or location?	YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>	Was the examination carried out: Within an interval of 6 months? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> With an interval of 12 months? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	In accordance with an examination scheme? YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> After the occurrence of exceptional circumstances? YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?	YES <input type="checkbox"/>	NO <input type="checkbox"/>		
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE				
Is the above a defect which is of immediate danger to persons:			YES <input type="checkbox"/>	NO <input checked="" type="checkbox"/>
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)			YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:				
Particulars of Any Tests Carried Out As Part of The Examination: (If None State NONE) The Subject Items Were Inspected Visually and Dimensionally Where no Signs of Defects Were Observed At The Time of Inspection And Found Satisfactory:				
IS THIS EQUIPMENT SAFE TO OPERATE?			YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>

REV: 01 Dated: 20 June 2022

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Thorough Examination:
Mohamed Abdulla	Ashraf El Said		27-Dec-2024

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

