



## CERTIFICATE OF THOROUGH EXAMINATION


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch			<b>Certificate No:</b>	QC-ZPEC-06-24-0190-04
<b>Examination Date:</b>	28-Jun-2024	<b>Rig &amp; Location:</b>	ZPEC – 25 RU – 620	<b>Job Number:</b>	QC-ZPEC-06-24-0190
<b>Last Inspection:</b>		<b>Next Inspection Due Date:</b>		<b>Last Proof Load Test:</b>	
Dec-2023		27-Dec-2024		By Manufacture:	
<b>Identification No:</b>	<b>Description Of Equipment:</b>			<b>QTY:</b>	<b>SWL:</b>
0050 0166 0063 0040 0168 0036 0032 0020 0036 0008	<u><b>Full Body Safety Harness Polyester Web.</b></u> <b>Manufacture:</b> Karam <b>Size Range:</b> 70 to 120 cm <b>Size:</b> Universal <b>Model:</b> WKPM52 <b>Location:</b> Rig HSE Store:			10	23 KN
<b>Reference Standard:</b>	BS EN 361:2002				

### RESULTS INSPECTION ON THE SAFETY BODY HARNESS ACCEPTANCE AS FOLLOWS:

Item	Inspection Point:	Yes	No
1	EXTENDED BACK D-RING	√	—
2	BACK PADDING	√	—
3	OVERSIZED ID TAG	√	—
4	WEB FINIAL	√	—
5	CAM BUCKLE	√	—
6	ENHANCED LUMBAR PADDING	√	—
7	SEAT SLING WITH SIDE D-RING	√	—
8	LEG PADDING	√	—
9	TONGUE BUCKLE LEGS	√	—
10	REMOVABLE BELT WITH LEATHER GUIDE	√	—
11	MESH BACK SHIELD	√	—

Item	Inspection Point:	Yes	No
12	MATING BUCKLE CHEST STRAP	√	—
13	INTEGRAL LABEL PACK	√	—
14	FRONT D-RING	√	—
15	PATENTED DURAFLEX STRETCHABLE WEBBING	√	—
16	STAND UP BACK D-RING	√	—
17	OPTIONAL BOS'N CHAIR WITH SIDE D-RING	√	—

<b>ASNT Level II Inspector Name:</b>	<b>Authenticating This Report:</b>	<b>Signature &amp; Stamp:</b>	<b>Client Name:</b>
<b>Mohamed Abdulla</b>	<b>Ashraf El Said</b>		<b>ZPEC</b>

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.