


CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	22/07/2024	Date of Next Examination	21/01/2025	Certificate No:	QC-24-HA-2207-006
Client Name:	HALLIBURTON	Location:	WPS WORKSHOP	Job Number:	22072024WPS
Serial Number:	QTY	Description	SWL	Manufacturing Date if known:	Date of last Examination
17124	1	LOADCELL P/N: TLG-30A/7075 HES: 101298147 FOS: 4:1	30,000 LBS	N/A	01/02/2024
Reference Standard:	HAL DOC: ST-GL-HAL-HSE-0420				
Is this the first examination after Installation or assembly at a new site or location?		YES	NO	✓	Was the examination carried out:
					Within an interval of 6 months?
					With an interval of 12 months?
If the answer to the above question is YES has the equipment been installed correctly?		YES	NO		In accordance with an examination scheme?
					After the occurrence of exceptional circumstances?
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect:					NONE
Is the above a defect which is of immediate danger to persons:					YES
Is the above a defect which is not yet but could become a danger to persons					N/A
Particulars of any tests carried out as part of the examination: (If none state NONE)					
The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?					YES
Inspector Name:	Authenticated By:	Signature & Stamp:	Client Signature & Stamp:	QR CODE	
ASHRAF ELSAID	AIZAZ FARHAT		ALI Talib HB48903 Date: 23-07-2024 Signature  Haliburton		

REV: 02 Dated: 01 NOV 2023

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

