



### CERTIFICATE OF THOROUGH EXAMINATION


This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

<b>Client Name:</b>	Zhongman Petroleum Engineering Technology Service (Hong Kong) Co. Limited Iraq Branch		<b>Certificate No:</b>	QC-ZPEC-06-24-0190-07	
<b>Examination Date:</b>	28-Jun-2024	<b>Rig &amp; Location:</b>	ZPEC - 25 RU - 620	<b>Job Number:</b>	QC-ZPEC-06-24-0190
<b>Last Inspection:</b>		<b>Next Inspection Due Date:</b>		<b>Last Proof Load Test:</b>	
Dec-2023		27-Dec-2024		By Manufacture	

Identification No:	Description Of Equipment:	QTY:	SWL:
0008 0009 0007 0010 0005 0006 0272 0602	<p align="center"><b><u>SHOCK ABSORBER LANYARD</u></b></p> <p align="center">Manufacture: KARAM Length: 1.8 M Size: Universal Material: Polyester Location: Rig HSE Store:</p>	08	23 KN
<b>Reference Standard:</b>	BS EN 354:2010		

**RESULTS INSPECTION ON THE SAFETY BODY HARNESS ACCEPTANCE AS FOLLOWS:**

Item	Inspection Point	Yes	No
1	TOP TERMINATION	√	-
2	LANYARD	√	-
3	BOTTOM TERMINATION	√	-
4	LABLE & TAGS	√	-
5	TOP TERMINATION	√	-
6	LANYARD	√	-
7	SNAP HOOKS	√	-
8	CARABINEERS	√	-
9	D-RINGS	√	-

<b>ASNT Level II Inspector Name:</b>	<b>Authenticating This Report:</b>	<b>Signature &amp; Stamp:</b>	<b>Client Name:</b>
Mohamed Abdulla	Ashraf El Said		<b>ZPEC</b>

**THIS IS TO CERTIFY THAT;** a competent person did attend the above-mentioned owner’s work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation “LOLER”. The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.