




Visual & Magnetic Particles Examination Report

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-07-0201-01
Date of Examination:	14.07.2024	Location:	HH Rig 029
Certificate No:	QC-HH-07-0201-02/61		
Serial Number	Description of the examined equipment		Result
HH-ZGF278-19-016	Dog House Lifting Lugs		Pass
Lifting Lugs SN:	2-1 , 2-2 , 2-3 , 2-4	Each Lug SWL:	40 KN



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-10	Due Date	12-08-2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06-2025
Black Ink	7HF	Batch No:	220605	Due Date	7-1-2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mohamed Abdalla	Ashraf Alsaid		13.01.2025


REV: 01 Dated: 20 June 2022






Visual & Magnetic Particles Examination Report

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-07-0201-01
Date of Examination:	14.07.2024	Location:	HH Rig 029
Certificate No:	QC-HH-07-0201-02/62		
Serial Number	Description of the examined equipment		Result
HH-ZGF277-19-017	Dog House Lifting Lugs		Pass
Lifting Lugs SN:	1-1 , 1-2 , 1-3 , 1-4 , 1-5 , 1-6 , 1-7 , 1-8	Each Lug SWL:	40 KN



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-10	Due Date	12-08-2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06-2025
Black Ink	7HF	Batch No:	220605	Due Date	7-1-2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mohamed Abdalla	Ashraf Alsaid		13.01.2025

REV: 01 Dated: 20 June 2022






Visual & Magnetic Particles Examination Report

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-07-0201-01
Date of Examination:	14.07.2024	Location:	HH Rig 029
Certificate No:	QC-HH-07-0201-02/63		
Serial Number	Description of the examined equipment		Result
19050	BOP Control System Lifting Lugs		Pass
Lifting Lugs SN:	1-1, 1-2, 1-3, 1-4		



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-10	Due Date	12-08-2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06-2025
Black Ink	7HF	Batch No:	220605	Due Date	7-1-2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mohamed Abdalla	Ashraf Alsaid		13.01.2025

REV: 01 Dated: 20 June 2022






Visual & Magnetic Particles Examination Report

Client Name:	Hong Hua Oil& Gas Engineering Services Ltd	Job Number:	QC-HH-07-0201-01
Date of Examination:	14.07.2024	Location:	HH Rig 029
Certificate No:	QC-HH-07-0201-02/64		
Serial Number	Description of the examined equipment		Result
190416	Pipe Rack Lifting Lugs		Pass
Lifting Lugs SN:	190416-1 To 190416-8	Each Lug SWL:	1200 KG



NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-10	Due Date	12-08-2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06-2025
Black Ink	7HF	Batch No:	220605	Due Date	7-1-2025
NDT procedure					
Visual and MPI carried out for the above description and found free of surface defects at the time of inspection					
Identification of any part found to have a defect and a description of the defect:					
None					
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
None					

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mohamed Abdalla	Ashraf Alsaid		13.01.2025

REV: 01 Dated: 20 June 2022

