




## Visual & Magnetic Particles Examination Report

Client Name:	<b>DAQING DRILLING COMPANY, Iraq</b>		Job Number:	DQ022-RUM-QC-OPS-2024071702	
Date of Examination:	20-July-2024	Location:	DQ – 022	Certificate No:	QC-DQ-07-24-0205-112
Unit Serial Number:	Description of The Examined Equipment:			Result	
22-H-453	Forklift Arms			Pass	



### NDT Equipment Details

Standard	ASTM E 709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-09	Due Date	12-Aug-2024
White Contrast	WCP-2	Batch No:	220602	Due Date	Jun-2025
Black Ink	7HF	Batch No:	220605	Due Date	Jan-2025

### NDT Procedure:


\*\*\*Visual and MPI Carried Out For The Above Description and Found Free of Surface Defects At The Time of Inspection:

Identification of Any Part Found To Have A Defect And A Description of The Defect:

**None:**

\*\*\*Particulars of Any Repair, Renewal or Alteration Required To Remedy The Defect Identified Above:

**None:**

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mohamed Abdulla LEEA Registered Technician	Ashraf El Saad LEEA Registered Technician		19-Jan-2025

REV: 01 Dated: 20 June 2022