



中国石油大庆油田
PETROCHINA DAQING OILFIELD

Inspection Service

This Service Presented To

DAQING

Inspection Service:

Rig Lifting Gear:

Customer:

DAQING DRILLING COMPANY, Iraq

Work Location:

DQ – 022 / RU – 623

Inspection Date:

20 – July – 2024

Next Inspection Date:

19 – Jan – 2025

Inspector Name:

Syed Aamir Ali:




Inspection Summary Report


Report No:	QC-DQ-07-24-0205	Job No:	DQ022-RUM-QC-OPS-2024071702
Customer:	DAQING DRILLING COMPANY, Iraq	Examination date:	20-July-2024
Location:	DQ – 022 / RU – 623	Next Due date:	19-Jan-2025



Equipment Details:

Name of The Examined Equipment:	Drum Lifter:
---------------------------------	--------------

Summary of Procedures:

Description of Step:	Status	Remark
Visually Check For Any Damage Wear Distortionetc.	✓	Pass
Check The Marking of Serial Number:	✓	Pass
Check The Marking of Manufacture:	✓	Pass
Is This Equipment Safe To Operate:	✓	Pass
Is This Equipment Inspected Visually and Dimensionally:	✓	Pass
At The Time Of Inspection Found Satisfactory:	✓	Pass

Inspector Name & Qualification: Mohamad Abdullah: ASNT Level II VT,MT,PT,UT, LEEA Level I,II	Signature & Stamp 
---	--





CERTIFICATE OF VISUAL AND THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulation

Report No:	QC-DQ-07-24-0205-121	Job No:	DQ022-RUM-QC-OPS-2024071702
Customer:	DAQING DRILLING COMPANY, Iraq	Examination date:	20-July-2024
Location:	DQ - 022 / RU - 623	Next Due date:	19-Jan-2025
Serial Number:	QTY	Description:	SWL: Date of Last Thorough Examination:
223	01	DRUM LIFTER Two-Leg Chain Drum Lifter Connected with Two Drum Lifter Clamp Dia: 7 mm Length: 0.7 M Location: Rig Store	01 Ton Feb-2024
Reference Standard:		BS ISO 3874:2017 / BS EN 13155:2020	
Is This the First Examination After Installation or Assembly at a New Site or Location?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Was The Examination Carried out: Within an Interval of 6 Months?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
		With an Interval of 12 Months?	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>
If the answer to the above question is YES has the equipment been installed correctly?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>	In Accordance with an Examination Scheme? After the Occurrence of Exceptional Circumstances?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE			
Is the Above a Defect Which is of Immediate Danger to Persons:	YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		
Is the Above an Affect Which is not yet but Could Become a Danger to Persons (If YES State the Date by When)		YES by:	
Particulars of any Repair, Renewal or Alteration Required to Remedy the Defect Identified Above:			
Particulars of any tests Carried out as Part of the Examination: (If none state NONE) <i>The Items Were Inspected Visually and Dimensionally Where No Signs of Defects Were Observed at The Time of Inspection Found Satisfactory:</i>			
Visual and Dimension Checks was Carried Out.	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		
IS THIS EQUIPMENT SAFE TO OPERATE?	YES <input checked="" type="checkbox"/> NO <input type="checkbox"/>		

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:
Mohamed Abdulla LEEA Registered Technician	Ashraf El Saad LEEA Registered Technician	

REV: 01 Dated: 20 June 2022

