

AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	03/09/2024	Date of Report:	03/09/2024	Certificate No:	QC-24/-CMT-0309-002
Client Name:	HALLIBURTON	Location:	CMT WORKSHOP	Job Number:	030924
Last Inspection		Last Proof Load Test Date		Next Proof Load Test Due	
05/03/2024		05/04/2023		04/04/2025	
Serial Number:	QTY	Description			SWL
CMT-3004 (38011-43) CMT-3034 (B2331790-13)	2	SWIVEL HOIST RING Manufacturer: Heavy Duty Type: Alloy Steel Heat Treated Range of Movement: Swivel 360° Pivot 180° Under Load FOS: 5:1			3000 LBS
Reference Standard:		HALLIBURTON PROCEDURE: ST-GL-HAL-HS-0206 REV. 4, 431.00005 REV. D, 431.00001 REV. G./ ASME B30.26			
Is this the first examination after Installation or assembly at a new site or location?		YES ☐ NO ☒		Was the examination carried out: Within an interval of 6 months? YES ☒ NO ☐ With an interval of 12 months? YES ☐ NO ☒ In accordance with an examination scheme? YES ☒ NO ☐ After the occurrence of exceptional circumstances? YES ☐ NO ☒	
If the answer to the above question is YES has the equipment been installed correctly?		YES ☐ NO ☐			
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES ☐ NO ☒	
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE) ** The subject Items were inspected Visually and dimensionally where no signs of defects were observed at the time of inspection and found satisfactory ** MPI was carried out on the Critical Areas and found satisfactory					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES ☒ NO ☐	
Name of Inspector:	Name of person authenticating this report:		Client Signature & Stamp:		
ASHRAF ELSAID	AIZAZ FARHAT		 		
Date of Next Through Examination	02/03/2025				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did at the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

