



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	27-Aug-2024	Date of Report:	27-Aug-2023	Certificate No:	QC-08-24-197
Client Name:	AMJAAD AL AASEMA CO.Iraq	Location:	Amjaad Al Aasema Yard	Job Number:	QC-08-24-1987
Equipment Serial No:	5344 / V100X337	Registration #	82565-K Bagdad	SWL:	10 Ton
Description of Equipment	Diesel Engine Powered Hydraulic System Wheel Loader Forklift Truck. Model: FD 100T-6 Max Capacity: 10 TON Max Lift: 3.7 Meter Manufacturer: KOMATSU UTILITY CO.LTD JAPAN Year of Mfg. : May-2013 Truck Weight: 17550 Kg				
Ref. Standard	BS ISO 2330:2002 / BS ISO 5057:1993				
Date of Last Examination:	NIL				
Examination Type	Pass	Fail	Notes		
Operational (No Load)	√		Forklift Found Satisfactory For Further Use.		
Performance Test (Rated Capacity)	√		Forklift found to be acceptable to lift 100 % from SWL.		
Proof Load Test (1.1 x Rated Capacity)	-	-	N/A		
Is this the first examination after Installation or assembly at a new site or location?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		Was the examination carried out:	
				Within an interval of 6 months?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
If the answer to the above question is YES has the equipment been installed correctly?		<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √		In accordance with an examination scheme?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
				After the occurrence of exceptional circumstances?	
				<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO <input type="checkbox"/> √	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none state NONE) NONE					
Is the above a defect which is of immediate danger to persons:				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/> √
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				N/A	
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
In the light of inspection findings, the subject Forklift was Inspected visually, and operationally and a performance test was performed where no defects were observed during testing Hence, it was found satisfactory and fit for the intended use.					
IS THIS EQUIPMENT SAFE TO OPERATE?				<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/> √
Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:			
Aizaz Farhat	Ashraf Esaid				
Date of Next Through Examination:	26-Aug-2025				

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Amjaad Al Aasema	Location:	Amjaad Al Aasema Yard	Examination Date:	27-Aug-2024
Equipment Serial No:	5344 / V100X337	Registration #	82565-K Bagdad	SWL:	10 Ton
Description of Equipment:	<u>Diesel Engine Powered Hydraulic System Wheel Loader Forklift Truck.</u>				

No	COMPONENT CHECKS	RESULT	COMMENTS
DATA PLATE			
1	Manufacturers data plate	√	
MAST/Boom			
1	Operation	√	
2	Structure and welds	√	
3	Rollers & bearings	N/A	
4	Main hoist cylinder(s)	√	
5	Load chains	N/A	
6	Anchor pins	√	
7	Tilt cylinders	√	
8	Hydraulic hoses	√	
9	Side shift	√	
FORKS			
1	Condition	√	
2	Heel wear	√	
3	Locking pins	√	
POWER PACK			
1	Operation	√	
2	Engine/motor	√	
3	Mountings	√	
4	Battery	√	
5	Wiring	√	
6	Hydraulic pump	√	
7	Isolation switches	√	
STEERING AND WHEELS			
1	Operation	√	
2	Steering cylinders	√	
3	Braking system	√	
4	Ball joints	√	
5	Wheel bearings	√	



THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF THOROUGH EXAMINATION



This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Amjaad Al Aasema	Location:	Amjaad Al Aasema Yard	Examination Date:	27-Aug-2024
Equipment Serial No:	5344 / V100X337	Registration #	82565-K Bagdad	SWL:	10 Ton
Description of Equipment:	<u>Diesel Engine Powered Hydraulic System Wheel Loader Forklift Truck.</u>				
6	Tire condition		√		

No	COMPONANT CHECKS	RESULT	COMMENTS
CABIN & CONTROLS			
1	Condition	√	
2	Control levers	√	
3	Control pedals	√	
4	Internal/external lights	√	
5	Gauges	√	
6	Seat and seat belt	√	
7	Horn	√	
8	Windscreen and wipers	√	
OTHER			
1	Light Alarm	√	
2	Sound Alarm	√	

Key Category:

1 = Immediate action	2= Action within ...	3= Worn/Serviceable	<input type="checkbox"/>	No Apparent Defects	N/A = Not Applicable
----------------------	----------------------	---------------------	--------------------------	---------------------	----------------------

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
Aizaz Farhat	Ashraf Esaid		
Date of Next Through Examination:	26-Aug-2025		

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Amjaad Al Aasema	Location:	Amjaad Al Aasema Yard	Examination Date:	27-Aug-2024
Equipment Serial No:	5344 / V100X337	Registration #	82565-K Bagdad	SWL:	10 Ton
Description of Equipment:	<u>Diesel Engine Powered Hydraulic System Wheel Loader Forklift Truck.</u>				



THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

