


CERTIFICATE OF VISUAL & THOROUGH EXAMINATION & NDT FOR HYDRAULIC DOZER

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Aberdeen Technical Services Co.			Certificate No:	QC-ATS-06-24-0112/01
Date of Examination:	28.06.2024	Location:	Aberdeen Yard	Job Number:	QC-ATS-06-24-0112
Equipment Serial No:	1FH00852			SWL:	--
Description of Equipment	DIESEL POWERED CRAWLER DOZER Manufacture: Caterpillar Model: D8N Chasses NO: 91C02826 Net Power: 240 HP Engine o: 31760 Engine Model: 3306T No. of cylinder: 06 Hydraulic pump flow: 46.8 gal/min Registration No: T12206-BAGDAD				
Ref. Standard	BS EN 474-2:2006+ A1:2008				
Date of Last Examination:	09/April/2023		Date of Last Proof Load Test:	N/A	
NDT Equipment Details					
Standard	ASTM E709	Viewing Condition:	Colored Media	Method	WET
Yoke	Permanent	Serial No:	PY-011	Due Date	14-08-2024
White Contrast	WCP-2	Batch No:	220602	Due Date	06-2025
Black Ink	7HF	Batch No:	220605	Due Date	7-1-2025
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out: Within an interval of 6 months?	
				With an interval of 12 months?	
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme?	
				After the occurrence of exceptional circumstances?	
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE					
Is the above a defect which is of immediate danger to persons:				YES	NO
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)				YES by:	
Particulars of any repair, renewal or alteration required to remedy the defect identified above:					
Particulars of any tests carried out as part of the examination: (If none state NONE)					
<i>*In the light of inspection findings subject Dozer was Visually and Functionally inspected and found Satisfactory & MPI Test</i>					
IS THIS EQUIPMENT SAFE TO OPERATE?				YES	NO

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mahmoud Ali	Mohamed Abdulla		27.06.2025

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.


CERTIFICATE OF VISUAL & THOROUGH EXAMINATION & NDT FOR HYDRAULIC DOZER

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Aberdeen Technical Services Co.	Location:	Aberdeen Yard
Description of Equipment:	DIESEL POWERED CRAWLER DOZER	Serial No:	1FH00852
Date of Examination:	28.06.2024	Certificate No:	QC-ATS-06-24-0112/01
		SWL:	--

Crawler Dozer Inspection Checklist

No	COMPONANT CHECKS	RESULT	COMMENTS
DATA PLATE			
1	Manufacturers operation manual	N/A	
2	Steering system	✓	
3	Brake System	✓	
4	Hydraulic oil level	✓	
5	Condition of oil	✓	
6	System and hoses	✓	
7	Lubrication	✓	
8	Engine Indication	✓	
9	Structure	✓	
10	Control levers	✓	
11	Track Roller frame	✓	
12	Wear , damage , cracks , leaks	✓	
13	Bucket	✓	
14	Pins , Grease lines	✓	
15	Tracks/Crawler	✓	
16	Windows I Mirrors I Lights	✓	
17	Undercarriage (including leaks)	✓	
18	Belts I Hoses I Bolts	✓	
19	Electrical System	✓	
20	Electric battery system	✓	
21	Power Unit	✓	
22	Power Link	✓	
23	Motion Alarm	✓	
24	Main, Frame	✓	

NOTE:

* Crawler Dozer visual, function & performance test were carried out and found accept at the time of inspection.& MPI Test

Key Category:

1 = Immediate action	2= Action within ...	3= Worn/Serviceable	✓	No Apparent Defects	N/A = Not Applicable
-----------------------------	-----------------------------	----------------------------	---	----------------------------	-----------------------------

ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mahmoud Ali	Mohamed Abdulla		27.06.2025

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



CERTIFICATE OF VISUAL & THOROUGH EXAMINATION & NDT FOR HYDRAULIC DOZER

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	Aberdeen Technical Services Co.	Location:	Aberdeen Yard
Description of Equipment:	DIESEL POWERED CRAWLER DOZER	Serial No:	1FH00852
Date of Examination:	28.06.2024	Certificate No:	QC-ATS-06-24-0112/01
		SWL:	--

PICTORIAL



ASNT Level II Inspector Name:	Authenticating This Report:	Signature & Stamp:	Date of Next Through Examination:
Mahmoud Ali	Mohamed Abdulla		27.06.2025

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.