

AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Date of Examination:	28-08-2024	Date of Report:	28-08-2024	Certificate No:	QC-ATS-08-24-0134/02		
Client Name:	ABERDEEN CO.	Location:	ABERDEEN YARD	Job Number:	QC-ATS-08-24-0134		
Equipment Serial No:	80C5-0727	Model No:	80ZV-2	SWL:	5 TON		
Description of Equipment	Diesel Engine Powered Hydraulic System Wheel Loader Forklift Truck. <i>Max Capacity: 5000 KG</i> <i>Chassis no: 80C5-0727</i> <i>Manufacturer : KAWASAKI</i> <i>Manufacture Date: 2016</i> <i>Plate No: A 54006 - Basra</i> <i>Grapple No: FSF00100</i>						
Ref. Standard	BS ISO 2330:2002, BS ISO 5057:1993 & 3691-1:2015+A1:2020						
Date of Last Examination:	27-08-2023		Date of Last Proof Load Test:	28-03-2022			
Examination Type	Pass	Fail	Notes				
Operational (No Load)	✓		Forklift Found Satisfactory For Further Use.				
Performance Test (Rated Capacity)	✓	-	Forklift found to be acceptable to lift 100 % from SWL .				
Proof Load Test (1.1 x Rated Capacity)	-	-	Proof Load Test Shall Be Done After any Repair/ Modification				
Is this the first examination after Installation or assembly at a new site or location?	YES	NO	✓	Was the examination carried out:	YES	NO	✓
				Within an interval of 6 months?	YES	✓	NO
				With an interval of 12 months?	YES	✓	NO
If the answer to the above question is YES has the equipment been installed correctly?	YES	NO		In accordance with an examination scheme?	YES	✓	NO
				After the occurrence of exceptional circumstances?	YES		NO
Identification of any part found to have a defect which is or could not become a danger to persons and a description of the defect: (If none State NONE) NONE							
Is the above a defect which is of immediate danger to persons:						YES	NO
Is the above a defect which is not yet but could become a danger to persons (If YES state the date by when)						YES by:	
Particulars of any repair, renewal, or alteration required to remedy the defect identified above:							
Particulars of any tests carried out as part of the examination: (If none state NONE)							
In the light of inspection findings subject, Forklift was Inspected visually, and operationally and a performance test was performed where no defects were observed during testing Hence, it was found satisfactory and fit for the intended use.							
IS THIS EQUIPMENT SAFE TO OPERATE?						YES	NO
Name of Inspector:	Name of person authenticating this report:		Signature & Stamp:				
SYED AAMIR	AIZAZ FARAHT						
Date of Next Through Examination:	27-08-2025						

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN CO.	Location:	ABERDEEN YARD	Examination Date:	28-08-2024
Equipment Serial No:	80C5-0727	Model No:	80ZV-2	SWL:	5 TON
Description of Equipment:	Diesel Engine Powered Hydraulic System Wheel Loader Forklift Truck				

No	COMPONENT CHECKS	RESULT	COMMENTS
DATA PLATE			
1	Manufacturers data plate	✓	
MAST/Boom			
1	Operation	✓	
2	Structure and welds	✓	
3	Rollers & bearings	✓	
4	Main hoist cylinder(s)	✓	
5	Load chains	N/A	
6	Anchor pins	✓	
7	Tilt cylinders	✓	
8	Hydraulic hoses	✓	
9	Side shift	✓	
FORKS			
1	Condition	✓	
2	Heel wear	✓	
3	Locking pins	✓	
POWER PACK			
1	Operation	✓	
2	Engine/motor	✓	
3	Mountings	✓	
4	Battery	✓	
5	Wiring	✓	
6	Hydraulic pump	✓	
7	Isolation switches	✓	
STEERING AND WHEELS			
1	Operation	✓	
2	Steering cylinders	✓	
3	Braking system	✓	
4	Ball joints	✓	
5	Wheel bearings	✓	
6	Tire condition	✓	



THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657

Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN CO.	Location:	ABERDEEN YARD	Examination Date:	28-08-2024
Equipment Serial No:	80C5-0727	Model No:	80ZV-2	SWL:	5 TON
Description of Equipment:	<u>Diesel Engine Powered Hydraulic System Wheel Loader Forklift Truck</u>				

No	COMPONANT CHECKS	RESULT	COMMENTS
CABIN & CONTROLS			
1	Condition	✓	
2	Control levers	✓	
3	Control pedals	✓	
4	Internal/external lights	✓	
5	Gauges	✓	
6	Seat and seat belt	✓	
7	Horn	✓	
8	Windscreen and wipers	✓	
OTHER			
1	Light Alarm	✓	
2	Sound Alarm	✓	

Key Category:

1 = Immediate action	2= Action within ...	3= Worn/Serviceable	✓	No Apparent Defects	N/A = Not Applicable
----------------------	----------------------	---------------------	---	---------------------	----------------------

Name of Inspector:	Name of person authenticating this report:	Signature & Stamp:	
SYED AAMIR	AIZAZ FARAHT		
Date of Next Through Examination:	27-08-2025		

REV: 01 Dated: 20 June 2022

THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.



AI TAKAMUL COMPANY FOR ENGINEERING TESTS AND PROFESSIONAL SAFETY LIMITED

Basra, North Rumaila, Quality Control Yard - Iraq

Tel: +9647810009138 / +9647834964657




Email: OP@qualitycontrol-iraq.com / hany.akafi@qualitycontrol-iraq.com



CERTIFICATE OF THOROUGH EXAMINATION

This Certificate complies with the requirements of the Lifting Equipment Operations and Lifting Equipment Regulations

Client Name:	ABERDEEN CO.	Location:	ABERDEEN YARD	Examination Date:	28-08-2024
Equipment Serial No:	80C5-0727	Model No:	80ZV-2	SWL:	5 TON
Description of Equipment:	Diesel Engine Powered Hydraulic System Wheel Loader Forklift Truck				



THIS IS TO CERTIFY THAT; a competent person did attend the above-mentioned owner's work location on the date shown above and the equipment described in this report was tested & inspected as per the requirements of Lifting Operations Lifting Equipment Regulation "LOLER". The result was found Satisfactory at the time of Inspection and considered Safe for Lifting.

